

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 500540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 10 & 11

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4669)

-----

Set fir post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on W face, from which  
A fir, 18" dia., bears N.32°E., 62 lks., mkd: ¼ S BT.  
A yew, 8" dia., bears N.65°W., 50 lks., mkd: ¼ S BT.

---

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Frank Jones & W. Penley - Aug. 1968- C.S. File 54/72-20

-----

Found - Orig. 18", now 30" Fir, alive, N.32°E. 40.9 ft., bark scribe in poor condition.  
Orig. 8", now 14" Yew, alive, N.65°W. 33.0 ft. blaze decayed, no scribing.

Set - Brass Cap at Cor. Mkd: County Surveyors T26S R8W Office, 1968 S 10|S 11

New BTs- 7" Hemlock N.68°E., 2.4 ft. Mkd: "¼ S11 CS BT"  
18" Hemlock S.79°W., 13.1 ft. Mkd: "¼ S10 CS BT.

This corner lies on very gentle NW slope.

---

Douglas Co. Surveyor's Office - Crew: Stephen J. Flauser and Jeff Lorsung - 3/25/2026 - C.S. File 67/62-31

-----

Found - 2½" D.C.S.O. Brass cap proj. 6".  
COUNTY SURVEYORS OFFICE  
T26S R8W  
¼ S10|S11  
1968

18" yew N.61°W. 33.3 ft. (Rec. N.65°W. 33.0 ft.) blaze decayed. Add 3½" mag nail right side center.  
26" hemlock N.68°E. 2.4 ft. fully healed double blaze. Add 3½" mag nail right side center.  
39" hemlock S.79°W. 13.1 ft. no blaze visible. Add 3½" mag nail right side center.

New - Found 2 unrecorded Weyerhaeuser 2008 BTs.  
14" hemlock N.45°W. 20.9 ft. Scribed ¼ S10 BT on partly healed single blaze. Spike nail below face. Dist. to tip of nail.  
14" red alder, bark scribed ¼ S10 BT N.6°W. 16.5 ft. Spike nail dist to nail tip.

Notes - Mon. approx. 40 ft. north of gravel road.  
Compass decl. 14¼°E.  
TRIMBLE GEO XT POSITION  
43°.32337351 N. 123°.62442819 W.