

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 540400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 14 & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4666-7)

Set a fir post, 3 ft. long, 4" sq., 24" in the ground for 1/4 sec. cor. mkd 1/4 S on N face, from which
A cedar, 6" dia., bears N.72°W., 32 lks., mkd: 1/4 S BT.
A fir, 30" dia., bears S.78°W., 16 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Sept. 1968 - C.S. File 54/72-26

Found - Orig. 6" Cedar, now 16" Snag, 11' high, N.72°W. 21.1 ft., shows good scar.
Orig. 30", now 34" Fir Snag, S.78° W. 10.6 ft., open & find "1/4 S" scribe & reverse.
Set - Brass Cap at Cor. Mkd: County Surveyors T26S R8W Office 1/4 S 14
1968 S 23

New BTs- 10" W.Fir S.84°E., 70.8 ft. mkd: 1/4 S23 CS BT.
9" W.Fir N.52°E., 9.1 ft. mkd: 1/4 S14 CS BT.
This corner lies on southwest moderate slope.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/7/26 - C.S. File 67/62-39

Found - 2 1/2" D.C.S.O. brass cap proj. 13".
COUNTY SURVEYORS
OFFICE
T26S R8W
1/4 S14
S23
1968

Rotted and broken 13" x 11 ft. cedar snag N.72°W. 21.1 ft. X in bark.
Very rotted sawn 14" x 6 ft. fir stump S.78°W. 10.6 ft. (9.4 to W nail in face) Scribe gone, some axe marks on face.

New - 9" D. Fir N.48°E. 21.1 ft. scribed 1/4 S14 BT on double blaze.
7" D. Fir S.21°E. 18.3 ft. scribed 1/4 S23 BT on double blaze.
12" D. Fir S.29°W. 6.3 ft. scribed 1/4 S14 BT on double blaze.
6" D. Fir N.48°W. 8.9 ft. scribed X CS BT on high/low blaze.

Notes - 3 1/2" mag nails right side center of new BTs.
Mon is on gentle S.W. slope in large stand of older D. Fir reprod. Approx 175 ft. south from the middle of switchback in main gravel road.

Compass decl. 14 1/4°E.
TRIMBLE GEO XT POSITION
43°.30154649 N. 123°.61445921 W.