

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor Secs 23, 24, 25, & 26

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4653-4)

Set a cedar post, 3 ft. long, 4" sq., 24" in the ground for cor. of secs. 23, 24, 25, & 26, mkd T26S S24 on NE, R8W S25 on SE, S26 on SW & S23 on NW faces with 2 notches on S and 1 on E edges, from which

- A fir, 16" dia. bears N.78°E. 36 lks. mkd: T26S R8W S24 BT
- A fir, 36" dia. bears S.10°E. 50 lks. mkd: T26S R8W S25 BT
- A cedar, 6" dia., bears S.73°W., 108 lks., mkd: T26S R8W S26 BT.
- A fir, 30" dia. bears N.14°W. 31 lks. mkd: T26S R8W S23 BT

The post stands on the E. side of land slide containing about 80 acres and which produced the Lake (N.0°1'W., 6 chains from the ¼ corner between Secs. 25 & 26) above referred to.

Marvin C. Ramsey - For: J.H. Baxter & Co. - Wit: J. D Kirklin & James Goodin - July 6-29, 1960 - C.S. File 51/116-1

Determined from the only 2 extant original bts

- D.Fir, dead snag 38" bears N.14°W., 31 lks. with partial scribe marks.
- Cedar 20" bears S.73°E., 108 lks., healed.

Set an iron pipe 3' long 2" in dia., 28" in the ground mkd. RS 404, from which new BTs:

- 14" D.Fir bears N.68°E. 14 lks. mkd: T26S R8W S24 RS404 BT
- 12" D.Fir bears S.40°E. 27 lks. mkd: T26S R8W S25 RS404 BT
- 10" D.Fir bears N.49°W. 26 lks. mkd: T26S R8W S23 RS404 BT

Dependent resurvey by Peter A. Peterson & Daniel L. Berry, Cadastral Surveyors, under Group No. 739, surveyed May/July 1971 - (DCSO Records Vol. 37 Page(s) 15209-10)

The cor. of secs 23, 24, 25, & 26 ,perpetuated & recorded by the County Surveyor, in 1968, monumented with an iron pipe, 2" dia., firmly set, protruding 6" above ground, from which the remains of the orig. BTs:

- A cedar, 25" dia., bears S.72°W., 108 lks., with healed blaze.
- A broken fir stump, bears N.14°W., 31 lks., with a down & decayed fir alongside, 36" dia., with healed blaze.

and BTs mkd. by the County Surveyor, in 1968

- A fir, 15" dia. bears N.68°E., 14 lks., with healed blaze.
- A fir, 13" dia., bears S.40°E., 27 lks. with healed blaze.
- A fir, 12" dia., bears N.49°W. 26 lks., with healed blaze.

At the corner point

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 600300

PRIMARY CORNER DESCRIPTION Cor Secs 23, 24, 25, & 26

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:

T26S	R8W
S 23	S 24
S 26	S 25

1971

Deposit the iron pipe alongside the iron post.

Dan Saily, Lone Rock Timber Co. - Crew: Weston Addington, Ignacio Roman & Trevor Clemo - 7/2024 - M183-77

Found - 1971 BLM brass cap on iron pipe mkd T26S R8W S23 S24 S25 S26 1971 as per volume 37 pg 15209-15210.
17"x6' tall Cedar stump bears S.72½°W., 70.7', rec S.72°W., 71.3', 108 lks. Rotten face and BLM tag.
27" D..Fir bears N.68¾°E., 9.6', rec. N.68°E., 9.2' 14 lks., healed face and BLM tag.
21" D.Fir bears S.41°E., 17.7', rec. S.40°E., 17.8' 27 lks. Healed face and BLM tag

New - 21" D.Fir bears N.50¾°W., 20.5'. We scribe T26S R8W S23 BT and tag.
13" D.Fir bear S.80¾°W., 27.4'. We scribe T26S R8W S26 BT AND TAG.

Found rotten remains of stumps at N.49°W., and N.14°W ., but we did not tie. Corner lies on flat ground approximately 60' west of rock cliff face in open mature timber stand. Top of brass cap is 0.6' above ground level. We place a 5½' tall steel galvanized U-post 1.0' north.

2