

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4657-8)

Set fir post, 3 ft. long, 4" sq., 24" in the ground for ¼ sec. cor. mkd ¼ S on W face, from which
A hemlock, 18" dia., bears N.63°E., 28 lks., mkd: ¼ S BT.
A hemlock, 10" dia., bears N.23°W., 23 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - John Powell - Frank Jones - & W. Penley - Aug. 1968 - C.S. File 54/72-18

Found - Orig 18" now 24" hemlock alive N.63°E. 18.5 ft shows scars. We do not open. Rescribed: "¼ S13 CS BT"
Orig. 10" Hemlock, now 12" decayed stump, 18" high with "BT" scribe exposed, N.23°W., 15.2 ft.
Set - Brass cap at cor. mkd: County Surveyors T26S R8W Office 1968 ¼ S14|S 13
New BT - 44" D.Fir N.86°W., 24.9 ft. mkd: "¼ S14 CS BT"
This corner lies on moderate east slope in old growth timber.

Dependent resurvey by Peter A. Peterson & Daniel L. Berry, Cadastral Surveyors, under Group No. 739, surveyed May/July 1971 - (DCSO Records Vol. 37 Page(s) 15213-4)

The ¼ sec. cor. of secs. 13 & 14, perpetuated & recorded by Tracy in 1968, monumented with an iron post, 1½" dia. firmly set, protruding 8" above ground, w/brass cap (properly) mkd from which the remains of the original BTs
A hemlock, 27" dia., bears N.63°E., 28 lks., with healed blaze, re-marked by County Surveyor, ¼ S13 CS BT visible on open double blaze.
A decayed hemlock stump, 9" dia., bears N.23°W., 23 lks., with scribe marks BT visible on opened blaze.
and a BT mkd. by Tracy, in 1968
A fir, 45" dia., bears N.86°W., 39 lks., with scribe marks ¼ S14 CS BT visible on open blaze.

Douglas Co. Surveyors Office - R.B. Kimberling - P.L. Earle - S.J. Flause - 5/2/1978 - C.S. File 60/11-3

Found - A 1"x30" IP laying 6" underground in loose turf, 2.0 ft. from corner location marked "County Surveyor Office" T26S ¼ S14 S13 R8W 1968 BLM 1971. 1968
Orig. BT, a 18" now 27" Hemlock is uprooted with visible scribing "¼ S13 CS". Orig. position bears approx. N.63°E., 18.5 ft.
continued next page

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 14

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A 10" now 11" rotted Hemlock stump, with blazed and scribed "BT" section laying alongside, bears N.23°W., 15.2 ft.
A 44" D.Fir bears N.86°W., 24.9 ft. with a well healed blaze.
Set - I reset brass cap 4" above ground and stamp "Reset 1978".
New BTs- A 46" D. Fir bears N.82°E., 12.5 ft. I double blaze and scribe "¼ S13 CS BT".
A boat spike in center of a 34" Fir stump bears S.18½°W., 18.9 ft. marked "BO 1".
A boat spike in center of a 48" Fir stump bears S.76½°E., 30.0 ft. marked "BO 2".
Corner is at the North edge of a new clearcut unit and 120 ft. east of Road #26-8-13.1.

BLM resurvey by Timothy Moore, Cadastral Surveyor & Robert Browning, Survey Technician, under Group #1990, surveyed July 2001/Sept. 2002 - (DCSO records Vol. 54 Page(s) 21042)

The ¼ sec. cor. of secs. 13 & 14, monumented with an iron pipe, 1½" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd.
from which the remains of the an original BT
A roothole, bears N.63°E., 18.5 ft., with hemlock trunk, 38" dia., with no marks visible, alongside.
and the remains of a BT mkd. by Powell, (Peterson and Berry reported this tree as being mkd. by Tracy).
A sawed fir stump, 46" dia., bears N.86°W., 25.7 ft., with a healed blaze.
and the remains of BTs mkd. by Kimberling, in 1978
A sawed fir stump, 44" dia. bears S.77¼°E. 29.6 ft., with boat spike driven into center of stump, stamped BO2.
A sawed fir stump, 38" dia., bears S.19°W., 18.9 ft., with boat spike driven into center of stump, stamped BO1.
and new bearing trees
A fir, 8" dia., bears S.44°E., 10.8 ft., mkd. ¼ S13 BT.
A fir, 9" dia., bears S.37½°W., 15.3 ft., mkd. ¼ S14 BT.