

PRIMARY CORNER DESCRIPTION Cor Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4658)

Set fir post, 3 ft. long, 4" sq., 24" in the ground, for cor. of secs. 11, 12, 13, & 14, 125 ft. above branch, marked T26S S12 on NE, R8 BT S13 on SE, S14 on SW, & S11 on NW faces with 4 notches on S and 1 notch on E edges, from which

 A hemlock, 6" dia., bears N.52°E., 27 lks., mkd: T26S R8W S12 BT.

 A fir, 30" dia. bears S.60°E. 56 lks. mkd: T26S R8W S13 BT

 A chinquapin, 16" dia., bears S.60°W., 56 lks., mkd: T26S R8W S14 BT.

 A chinquapin, 10" dia., bears N.39°W., 42 lks., mkd: T26S R8W S11 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - Sept. 1968 - C.S. File 54/72-27

Found - Orig. 6" now 14" hemlock, alive, N.52°E., 17.8 ft., scribe visible on open blaze.

 Orig. 30" now 40" fir, alive S.60°E., 37.0 ft., shows good scars.

 Orig. 16" now 24" Chinquapin, S.56°W., rec. S.60°W., 37.0') 39.6 ft bearing & dist turned around. Alive scribe visible on nearly healed blaze (poor)

 No trace orig. NW BT.

Set - Brass cap to cor. mkd: County Surveyors T26S R8W
 Office S 11|S 12
 1968 S 14|S 13

New BTs- 18" Hemlock S.58°E., 32.8 ft mkd: T26S R8W S13 CS BT

 17" Hemlock N.17°E., 27.0 ft mkd: T26S R8W S12 CS BT

 5" D.Fir N.74°W., 17.6 mkd: S11 CS BT.

 Orig. 24" Chinquapin S.56°W., 39.6 ft. mkd: T26S R8W S14 CS BT.

This corner lies on top of Mt. in dense rhododendron thicket.

Dependent resurvey by Peter A. Peterson & Daniel L. Berry, Cadastral Surveyors, under Group No. 739, surveyed May/July 1971 - (DCSO Records Vol. 37 Page(s) 15214-5)

The cor. of secs. 11, 12, 13, & 14, perpetuated & recorded by Tracy, in 1968, monumented with an IP, 1½" dia., firmly set, protruding 12" above ground, with brass cap (properly) mkd. from which the remains of the original bearing tree

 A hemlock, 15" dia., bears N.48°E., 28 lks., with scribe marks 26S R8W visible on partially healed blaze, (Record, N.52°E., 27 lks.) continued next page

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor Secs 11, 12, 13, & 14

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

A fir, 47" dia., bears S.60°E., 56 lks. with healed blaze.
A chinquapin, 27" dia., bears S.53°W., 60 lks., with fragmentary scribe marks visible on partially healed blaze, re-marked by the County surveyor, in 1968, with scribe marks T26S R8W S14 CS BT visible on open blaze. and bearing trees mkd. by Tracy, in 1968
A hemlock, 18" dia., bears N.18°E., 42 lks., with scribe marks T26S R8W S12 CS BT visible on open blaze.
A hemlock, 18" dia., bears S.59°E., 50 lks., with scribe marks T26S R8W S13 CS BT visible on open blaze.
A fir, 5" dia., bears N.74½°W., 27 lks., with fragmentary scribe marks visible on pitched over blaze.

Ronald Geisler, LS 1988 - For: Champion International
Sept/Dec 1983 - M90-49

Found - 1968 Douglas Co. brass cap on 1½" IP
27" split chinquapin bears S.54°W. 39.60 ft (rec S.60°W. 37.0 ft.) scribed T26S R8W S14 CS BT (orig.)
15" rotten hemlock snag, 30 ft. tall, bears N.48°E., 18.5 ft. (Rec. N.52°E., 17.8 ft.) No scribing visible. (Orig)
48" fir stump bears S.60°E., 37.9 ft. (Rec. 37.0 ft.) No scribing visible (original)
21" hemlock bears S.59°E., 32.3 ft. (Rec. S.58°E., 32.8 ft) Scribe marks visible on open blaze.
18" hemlock snag, 30 ft. tail bears N.18°E., 27.7 ft. (Rec. 27.0 ft.) Scribe marks visible on open blaze. (1968)

New BTs- 15" chinquapin bears S.2°30'E., 38.2 ft. scribed T26S R8W S14
8" hemlock bears N.3°30'E., 30.5 ft. scribed T26S R8W S12 BT.

No BTs available in NW and SW quadrant.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flause and Jeff Lorsung - 3/26/26 - C.S. File 67/62-33

Found - 2½" D.C.S.O. brass cap proj. 14".
COUNTY SURVEYORS OFFICE
T26S R8W
S11|S12
S14|S13
1968
Fallen-rotted, mostly gone chinquapin S.54°W. 39.6 ft.

continued next page

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 600500

PRIMARY CORNER DESCRIPTION Cor Secs 11, 12, 13, & 14

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Rotting 48" x 3 ft. fir stump S.60°E. 37.9 ft. blaze not visible.
18" x 8 ft. broken off hemlock snag S.59°E. 32.3 ft. blaze rotted out.
Broken - rotted shell of 15" chinquapin S.2°30'E. 30.5 ft. fully healed single blaze. Add 3½" mag nail right side center.

New - Found 2 unrecorded Weyerhauser bearing trees.
9" hemlock, no blazing. Has spike set low facing corner. Bears S.73°E. 16.9 ft. dist to tip of spike.
12" x 6½ ft sawn D. Fir stump N.80°W. 14.2 ft. single blaze with scribing "T S11" Spike below blaze, dist to tip of spike.

Notes - Mon approx 45 ft. south from roughed in dirt road.
Mon is on nearly flat ridge top N.E. quad. Young fir plantation. S.E. quad is very old mixed reprod west half is large clearcut.

Compass decl. 14¼°E.
TRIMBLE GEO XT POSITION
43°.31614330 N. 123°.60462963 W.