

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 602600

PRIMARY CORNER DESCRIPTION Closing Corner Secs 1 & 2 (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by - A.R. & S.C. Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 11 Page(s) 4648)

Cor. to secs. 1, 2, 11, & 12, from which
A fir, 48" dia., bears S.85°W., 28 lks.
A W.Fir, 30" dia., bears S.70°E., 37 lks.
A fir, 36" dia., bears N.60°E., 58 lks.
A fir, 12" dia., bears N.30°W., 26 lks.

GLO survey by William P. Heydon, Deputy Surveyor, under contract No. 656, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4660-1)

Intersect 2.25 chs. W of cor of secs. 1, 2, 11, & 12. As this intersection indicates that the N. and S. bdys of sec. 12 are not within required limits & being satisfied of the correctness of my survey and having retraced the E. bdy of sec. 12 for the purpose of fixing the point at which to restore the cor. of secs 7, 12, 13, & 18, and finding no material error thereon. I therefore begin at the cor. of secs. 1, 2, 11, & 12, which is a post firmly set witnessed and marked as described the Surveyor General, and run thence N.0°34'W. on blank line bet, secs, 1 and 2. 79.87 (chs) intersect N bdy of the Tp 1.39 chs. E of co. to secs. 1, 2, 35, & 36. As this clearly demonstrates that the error is in the measurement of the line bet. secs. 1 & 12. I therefore at point of intersection.
I erase markings for secs. 11 & 12 on old post and trees.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - July/Aug. 1968- C.S. File 54/72-3

From the Closing Corner of Sections 11 & 12, we measure East 150.0 ft. & find the following:
Orig. 48", now 52" Fir, S.85°W. 18.5 ft. alive obliterated in 1896, old axe marks & possible fragmentary bark scribe.
Orig. 30" Fir S.70°E., 24.4 ft., only roots & decayed wood remain.
Orig. 36", now 40" Fir, N.60°E. 38.3 ft. At point for tree there is a hole, tree slid approx. 30 ft. downhill, no scribe found, burned.
Orig. 12" Fir N.30°W., 17.2 ft. point fails under log, we find burned & decayed remnants of old fir, no scribe.
Because the distance west to CC fits so closely & remains of possible orig. BTs, we renew:
Set - Brass Cap at Cor. mkd: - County Surveyors T26S R8W
(continued next page) Office, 1968 S 2 | S 1

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 602600

PRIMARY CORNER DESCRIPTION Closing Corner Secs 1 & 2 (South)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

New BTs- 8" Hemlock N.43°W. 24.8 ft. Mkd. T26S R8W S2 CS BT.
9" Hemlock N.57°E. 25.0 ft. Mkd. T26S R8W S1 CS BT.
This corner lies on moderate northerly- slope, 150 ft E of CC

Fd. & used on Dependent resurvey by Peter A. Peterson & Daniel L. Berry, Cadastral Surveyors, under Group No. 739, surveyed May/July 1971 - (DCSO Records Vol. 37 Page(s) 15216)

BLM Dependent resurvey by James E. Jelley & Wayne L Rogers, Cadastral Surveyor under Group #1128 surveyed Jan. 1983- (DCSO records Vol. 43 Page(s) 16755-6)

The cor. of secs. 1 & 2 only, bears N.89°23'E., 2.29 chs. (from the CC Secs. 11 & 12) perpetuated & recorded by Tracy, in 1968, monumented with an iron post, 1½" dia., firmly set, projecting 8" above ground, with brass cap (properly) mkd. from which the remains of the orig. BTs
A root hole, bears N.60°E., 58 lks.
A fir snag, 52" dia. bears S.85°W. 28 lks no marks visible and remains of bearing trees mkd. by Tracy
A hemlock, 14" dia. bears N.57°E. 38 lks. with fragmentary scribe marks visible on partially healed blaze.
A root hole, bears N.43°W., 38 lks., with down hemlock alongside, 12" dia., with healed blaze.
and a new bearing tree
A hemlock, 4" dia., bears N.87°W., 41 lks., mkd. X BT.

Douglas Co. Surveyor's Office - Crew: Stephen J. Flauser and Jeff Lorsung - 4/1/2026 - C.S. File 67/62-37

Found - 2½" DCSO brass cap proj 9" (properly mkd)
Very rotted 52"x 2' D.Fir stump S.85°W., 18.5 ft.
Shattered, rotted 12"x 2' Hemlock snag, N.57°E., 25.1 ft., fragmentary scribed visible.
17" Hemlock, N.87°W., 25.2 ft. (rec. 41 lks) blaze not visible.
New - Three unrecorded BTs. One unknown origin, 2 are 2023 Weyerhaeuser.
19" Hemlock, painted up as BT, no blaze evidence N.58°E., 33.4 ft.
6" D.Fir N.83°E., 32.3', (tag says S.83°W., 23.1, dist transposed?) scribed S11 BT on single blaze.
7" D.Fir S.51°W., 22.0 ft. (tag N.51°E., 21.5) scribed ¼ S1 BT on single blaze.
Note - Compass decl. 14¼°E.
Mon on moderate north slope in older reprod.
Trimble GEO XT position:
N 43.33091042° W 123.60399917°