

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24; 18, 19 of T26-7

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - Dennis Hathorn, under Contract #57 dated April 12, 1855 (DCSO records, Volume 11 Page 4590)

Set post, cor. secs. 18, 19, 13 and 24, from which
A Fir 40" dia., bears N.1°W., 66 lks. dist.
A Hemlock 18" dia., bears N.50°E., 62 lks. dist.
A Hemlock 6" dia., bears S.10°W., 22 lks. dist.
A Hemlock 6" dia., bears S.60°E., 34 lks. dist.

GL0 survey by S.C. Flint, under Contract #392 dated May 26, 1881 (DCSO records, Volume 11 Page 4619)

Made and set firmly in the ground, a Laurel post, 40" long, 4" square, from which the old witness trees bear as follows: (BTs as described by Hathorn)

Richard Grant; D. Powell; J. Champman; W. Oiler - For: Martin Bros. Box - Jan. 3, 1958 - C.S. File 42/328-3

Set 1" x 30" I.P. with brass cap mkd: T26S 13|18 T26S
R8W 24|19 R7W
from testimony of Jack Champman, Wayland Oiler & R.C. Grant, who had viewed original location of corner & witness trees, prior to corner being destroyed by a small slide on the Hubbard Creek Road.
No new trees available as area was burned and logged.

Bureau of Land Management survey by Lynn Roseberry, under Group #696. Survey July 1969 (DCSO records, Volume 36 Pages 14864-65)

Sec. corner, perpetuated and recorded by Richard C. Grant, in 1958, from testimony of long time local residents, monumented with an iron post, 1" dia., firmly set, projecting 12" above ground, with brass cap mkd. T26S R8W S13 S24 T26S R7W S18 S19 1969. (?)
from which new bearing trees:
A Fir 4" dia., bears N.81½°E., 36 lks. dist., mkd X BT.
A Fir 6" dia., bears S.86½°E., 200 lks. dist. mkd. T26S R7W S19 BT.
A Fir 4" dia., bears S.11°W., 8½ lks. dist., mkd. X BT.
A Fir 4" dia., bears N.81°W., 37 lks. dist. mkd. X BT.
Add marks B L M to brass cap.

(Cont. Next Page)

TOWNSHIP 26 RANGE 08 POINT IDENTIFIER # 700400

PRIMARY CORNER DESCRIPTION Sec. cor. 13 & 24; 18 & 19 of T. 26-7

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM resurvey by Peterson & Berry in 1971 under Group #739 found Brass cap and four BTs. (DCSO records, Volume 37 Pages 15198-99)

BLM Dependent resurvey by Timothy J. Moore, Cadastral Surveyor and Robert H. Browning, Survey Tech, under Group No. 2140 surveyed June/Aug. 2006- (DCSO records Vol. 57 Pg 22468)

The cor. of secs. 13, 18, 19, & 24, on the W. bdy. of the Tp. monumented with an iron post, 1" dia. firmly set, projecting 12" above the ground, with brass cap (properly) mkd.

from which bearing trees mkd. by Roseberry in 1969

A fir, 17" dia., bears N.81½°E., 23.8 ft., with a healed blaze.

A fir, 30" dia., bears S.85¾°E., 132.0 ft., with a healed blaze. (Record, S.86½°E.)

A fir, 14" dia., bears S.11°W., 5.6 ft., with a healed blaze.

A fir, 13" dia., bears N.81°W., 24.4 ft., with a healed blaze.