

TOWNSHIP 26 RANGE 09 POINT IDENTIFIER # 400240

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 27 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

**ON THE COOS COUNTY LINE - SEE COOS COUNTY SURVEYORS OFFICE FOR POSSIBLE ADDITIONAL RENEWAL REPORTS**

GLO survey by John W. Meldrum, Deputy Surveyor, under contract No. 662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4757)

-----  
Set a Vine maple post, 3 ft. long, 3" sq., 24" in the ground, for ¼ sec. cor., marked ¼ S on W side; from which  
A hemlock, 22" dia., bears N.10°W., 52 lks., mkd: ¼ S BT.  
A yew, 13" dia., bears N.85°E., 102 lks., mkd: ¼ S BT.

Corner report received from Coos Co. Surveyors Office, 12/1/2000 - M136-15 & C.S. File 65/29-11 - Survey by Theodore S. Ellingsen 5/1962

-----  
Set - 2" alum. pipe 3 ft. long were driven 2 ft. into the ground.

DCSO-GIS Corner visitation - 11/27/2000 - Typed: 1/27/2011 - C.S. File 67/33-1

-----  
Monument - IP