

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 15 & 16

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

ON THE COOS COUNTY LINE - SEE COOS COUNTY SURVEYORS OFFICE FOR POSSIBLE ADDITIONAL RENEWAL REPORTS

GLO survey by John W. Meldrum, Deputy Surveyor, under contract No. 662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4761)

Set fir post 3 ft. long, 3" sq. 24" in the ground for ¼ sec. cor. marked ¼S on W face, from which

- A fir, 20" dia., bears S.72°E., 21 lks., mkd: ¼ S BT.
- A fir, 30" dia., bears N.52°30'W., 31 lks., mkd: ¼ S BT.

Theodore S. Ellingsen - for Menasha Corp. 9/1962 - C.S. File 65/91-3 (rec'd from Coos Co. 2015)

The following notes describe the establishment of new bearing trees at the ¼ corner between Sections 15 and 16, T26S R9W, W. M., Coos County, Oregon:

I find the 28" Fir BT, S.72°E., 14.5 ft, now down, the scribe is plainly visible.

I also find the Fir BT, N.52°30'W., 21.0 ft, now a short stub with no visible marks.

From a 2" aluminum pipe which I set in place, I scribed the following:

- A 28" Hemlock N.50°W., 52.8 ft scribed E¼ S16 BT.
- A 24" Hemlock N.22°E., 25.3 ft scribed W¼ S15 BT.

Tony Hostetter - For: Weyerhaeuser Co. - May 14, 2015 - C.S. File 65/89-46

Found - 28" hemlock stump, scribing visible. Ellingsen

Set - 5/8"x36" iron rod w/alum cap mkd "T26S R9W S15 S16 ¼ LS1975 2015" from which

- 28" hemlock stump, Ellingsen BT, described above, bears N.22°00'E., 25.3' to center (rec. bearing & dist.)
- 44" Fir stump, WEYCO tag & "W" nail, bears S.15°18'E., 21.8 ft. to "W" nail (WEYCO rec. S.15°E., 21.8')

New BTs-

- 13" Fir scribed "S15 ¼ BT" BT tag, bears N.17°15'E., 17.1 ft. to spike.
- 14" Fir scribed "S15 ¼ BT" BT tag, bears N.86°04'E., 6.0 ft. to spike.
- 15" Fir, scribed "S15 ¼ BT" BT tag, bears S.33°54'E. 10.3 ft. to spike.
- 8" double alder scribed "S16 ¼ BT" BT tag, bears S.56°08'W., 14.4 ft. to spike.