

TOWNSHIP 26 RANGE 09 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Cor. Secs. 3, 4, 9, & 10

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

ON THE COOS COUNTY LINE - SEE COOS COUNTY SURVEYORS OFFICE FOR POSSIBLE ADDITIONAL RENEWAL REPORTS

GLO survey by John W. Meldrum, Deputy Surveyor, under contract No. 662, dated May 21, 1896 - (DCSO records Vol. 11 Page(s) 4763-4)

Set maple post 3 ft. long, 3" sq., 24" in the ground for cor. of secs. 3, 4, 9, & 10, marked T26S, S3 on NE, R9W, S10 on SE, S9 on SW & S4 on NW faces, with 5 notches on S & 3 notches on E edges, from which

- An alder, 11" dia., bears N.40°E., 14 lks., mkd: T26S R9W S3 BT.
- A fir, 60" dia., bears S.7°E., 33 lks., mkd: T26S R9W S10 BT.
- A cedar, 14" dia., bears S.43°W., 82 lks., mkd: T26S R9W S9 BT.
- A fir, 24" dia., bears N.39°20'W., 83 lks., mkd: T26S R9W S4 BT.

Robert C. Adamek, Weyerhaeuser Co. Dellwood Engineering Office Williams River No. 2 survey - March 27, 1975 - M55-60 & C.S. File 58/42

The orig. cor & accessories were destroyed by rd construction Before its destruction, the corner was re-referenced by Weyerhaeuser Co. Engineers.
1" IP from which
36" R.Cedar, bears N.78°E., 59.0 ft.
36" D.Fir, bears N.39°W., 21.8 ft.