

PRIMARY CORNER DESCRIPTION SE. Cor. Sec. 36 (Tsp. Cor.)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by - A. R. and S.C.Flint, Under Contract #392, dated May 26, 1881 (DCSO records Vol. 11 Page(s) 4644)

-----  
Cor. to secs. 1, 6, 31 and 36, being corner to Tps. 26 and 27 S., Rs. 8 and 9 West. AT which I set firmly in the ground, a Laurel post 4 ft. long, 4" sq., from which

- A Fir 20" dia., bears N.70°W., 37 lks. dist.
- A Laurel 6" dia., bears S.10°E., 26 lks. dist.
- A Laurel 6" dia., bears S.25°W., 54 lks. dist.
- A Laurel 6" dia., bears N.85°E., 57 lks. dist.

GLO survey by William P. Heyden, Deputy Surveyor, under contract #656, dated May 21, 1896 - (DCSO records Vol. 13 Page(s) 5293)

-----  
Cor. to Tps. 26 and 27 S., Rs. 8 and 9 W.; set by Flint about 15 years ago, bears W. 4 lks. dist. The post still standing but badly decayed. As my falling is so small, I do not establish a closing corner. I set new post, Fir, 3 ft. long, 6" sq., 24" in the ground for corner, marked T26S S31 on NE.; R8W S6 on SE.; T27S S1 on SW.; and R9W S36 on NW. faces, with 6 notches on each edge, from which

- A Laurel 6" dia., bears N.85°E., 57 lks. dist.
- A Fir 20" dia., bears N.70°W., 37 lks. dist.
- A Laurel 6" dia., bears S.10°E., 26 lks. dist.
- A Laurel 6" dia., bears S.25°W., 54 lks. dist.

The four trees located above are the bearing trees described by the surveyor general. The blazes are distinctly visible, but the other marks are indistinct being more or less covered with new growth.

Survey by Robert C. Adamek - For: Weyerhaeuser Co. - (Elk Wallow Survey) July 13, 1977 - C.S. File 58/139 & M 66-12

-----  
Set by double proportion, a 2" brass cap monument, from which  
A 12" D.Fir bears N.76°W., 27.9 ft. scribed TWP Cor RP.  
42" D.Fir bears S.78°E., 50.1 ft. scribed TWP Cor RP.  
19" Fir snag bears N.21°E., 15.8 ft. scribed TWP Cor RP.  
13" Chinquapin bears N.89½°W., 27.1 ft. scribed TWP Cor RP