

TOWNSHIP 27 RANGE 01E POINT IDENTIFIER # 140400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 18 & 19

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Otto L. Draper, US Transitman, under Special Instructions dated Dec 24, 1920 - (DCSO records Vol 23 Pg 9930)

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for 1/4 sec. cor., with brass cap marked

1/4 $\frac{S\ 18}{S\ 19}$
1927

from which

A hemlock, 26" dia., bears N.54°E., 49 lks., mkd: 1/4 S18 BT
A hemlock, 26" dia., bears S.56°W., 49 lks., mkd: 1/4 S19 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - 10/22/1969 - C.S. File 52/77-21

Found - 1927 GLO Brass Cap tied to tree. Corner now falls in logging road.
26" Hemlock, now stump, S.56°W. 32.3 ft., scribe visible.
No trace of N. E. Bearing Tree.

Reset - GLO 1927 Brass Cap, remarked W C 35' North to.
New BTs- 34" Hemlock S.21°E. 34.0 ft. Mkd: W C 1/4 S19 CS BT
39" D.Fir S.44°W. 13.8 ft. mkd: W C 1/4 S19 CS BT.

This corner lies on top of cut bank 40.0 ft. S. of centerline of loggin road.

NOTE - This cor was reported as being the 1/4 WC cor of secs. 18 & 19, T26S R1W. Per research in the office & a visit by the field crew it was determined that is actually was the WC for the 1/4 cor. of secs. 18 & 19 T27S R1E. JC DCSO 7/15/2008

Douglas Co. Surveyors Office - John Pike - Kody Inda - 6/23/2008 - C.S. File 67/25-58

Found - 2 1/2" dia., brass cap mkd as per record on 1" O.D. IP projects 1 ft above ground firmly set. Cap is oriented to east.
39" now 43" dia., D.Fir fully healed double blaze bears S.44°W., 14.8 ft. (Rec. S.44°W., 13.8 ft.) 1969 BT.
34" now 35" dia., Hemlock partially healed double blaze scribing visible bears S.21°E., 34.0 ft. (Agrees w/rec) 1969 BT
Hemlock stump not looked for.
No new accessories were established.
Compass decl. 16 1/4°E.

1