

TOWNSHIP 27 RANGE 01E POINT IDENTIFIER # 804020

PRIMARY CORNER DESCRIPTION Cor. No. 2 Roy #3 Mill Site; MS 1008B

Alias _____	Description <u>Cor. No. 2 of the Roy #4 Mill Site</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18926)

Corner No. 2, identical with Cor. No. 2 of the Roy No. 4 mill site, of this survey.

This corner falls in a gravel road. Set a 5/8" dia. iron rod, 30" long, 4" below road surface, with a 1½" dia. aluminum cap mkd. R3-2 R4-2-MS1008B 1992, from which

A cedar, 6" dia., bears S.9°30"W., 45.20 ft., mkd. R3-2-1008B BT.

A fir, 6" dia., bears S.49°55"W., 48.80 ft., mkd. R4-2-1008B BT.