

TOWNSHIP 27 RANGE 01E POINT IDENTIFIER # 805020

PRIMARY CORNER DESCRIPTION Cor. No. 1 Roy #4 Mill Site; MS 1008B

Alias _____	Description <u>Cor. No. 1 Roy #5 Mill Site</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18927)

-----

Cor. No. 1 of the Roy No. 4 mill site, identical with Cor. No. 1 of the Roy No. 5 mill site, of this survey.

Set a 2½" dia. aluminum pipe, 30" long, 28" in the ground, with a 3" dia. aluminum cap mkd. R4-1 R5-1-MS1008B 1992, from which

The closing cor. of secs. 2 and 3, T28S R1E WM, bears S.81°13'38"E., 1712.40 ft.

A fir, 11" dia., bears S.24°10'E., 10.13 ft., mkd. R4-1-1008B BT.

A fir, 6" dia., bears S.43°00'W., 29.82 ft., mkd. R5-1-1008B BT.