

TOWNSHIP 27 RANGE 01E POINT IDENTIFIER # 806010

PRIMARY CORNER DESCRIPTION Cor. No. 3 Roy #5 Mill Site; MS 1008B

Alias _____	Description <u>Cor. No. 3 Roy #6 Mill Site</u>
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM Mineral Survey 1008 A&B by Richard C. Skinner, Mineral Surveyor, survey under order dated June 30, 1992, Survey of Mineral Claims of: Anna Lu Rannells, Surveyed July/Aug. 1992 - (DCSO records Vol. 50 Page(s) 18928)

Corner No. 3, identical with Cor. No. 3 of the Roy No. 6 mill site, of this survey.

Set a 2½" dia. aluminum pipe, 30" long, 26" in the ground, with 3" dia. aluminum cap mkd. R5-3 R6-3-MS1008B 1992, from which

- A fir, 12" dia., bears N.76°05'E., 20.85 ft., mkd. R5-3-1008B BT.
- A fir, 8" dia., bears N.38°50'W., 18.61 ft., mkd. R6-3-1008B BT.