

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31 only, (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by S.C. Flint, Contract #459, dated August 3, 1882
- (DCSO records Vol. 12 Page(s) 4873)

Set Cedar post 4 ft. long, 4" sq., 24" in the ground for cor.
to secs. 30, 31, 36 and 25 and mkd. T27S S30 on NE.; R1W S31
on SE.; R2W S36 on SW.; and S25 on NW. faces with 5 notches
on N. and 1 notch on S. edges, from which
A Fir 16" dia., bears N.55°E., 32 lks. dist. mkd. T27S R1W
S30 BT.
A White Pine 32" dia., bears S.45°E., 27 lks. dist. mkd.
T27S R1W S31 BT.
A Fir 30" dia., bears S.25°W., 36 lks. dist. mkd. T27S R2W
S36 BT.
A Fir 24" dia., bears N.80°W., 22 lks. dist. mkd. T27S R2W
S25 BT.

GL0 survey by Homer D. Angell, Deputy Surveyor, under
Contract #746, dated May 5, 1902 - (DCSO records Vol. 11
Page(s) 4781)

Set basalt stone 18x10x10 ins., 14" in the ground for cor. of
secs. 25, 30, 31 and 36, mkd. with 5 notches on N. and 1
notch on S. edges, from which
A Cedar 18" dia., bears N.46½°E., 60 lks. dist. mkd. T27S
R1W S30 BT.
A Hemlock 12" dia., bears S.22½°E., 39 lks. dist. mkd.
T28S R1W S31 BT.
A Hemlock 20" dia., bears S.62°W., 38 lks. dist. mkd. T27S
R2W S36 BT.
A Cedar 30" dia., bears N.69°W., 38 lks. dist. mkd. T27S
R2W S25 BT.
From this cor., the old cor. bears N.86°46'W., 272 lks. dist.
I destroy the cor.

GL0 survey by Morris Wygant, compassman for Zachariah M.
Derrick, U.S. Deputy Surveyor, under Contract #779, dated
Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4908)

The Sec. Cor., which is a stone, firmly set, marked and
witnessed as described by the surveyor general, and which I
now change to refer to secs. 30 and 31 T27S R1W only.

Douglas Co. Surveyors Office - Milo E. Godfrey, Deputy - M.
Stone, crew - Sept. 7, 1962 - C.S. File 49/28-5

This corner originally set as corner for secs. 25 and 36,
T27-2 and Secs. 30 & 31, T27-1. All 4 orig. trees found, but
(Cont. Next Page)

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 100200

PRIMARY CORNER DESCRIPTION Sec. Cor. for 30 & 31 only, (West)

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

bearings given are all wrong. The NW. tree is actually NE.
The SE. tree is actually SW. The SW. tree is actually NW.
The NE. should be SE.

Found - Cedar now 30", S.46½°E. (not N.46½°E.) 39.6 ft.,
scribing plainly visible on open face "T27S R1W
S31 BT".

Stump of 12" Hemlock S.22½°W. (not S.22½°E.) 25.7
ft. Axe marks on old face where scribing had been
cut off.

20" Hemlock N.62°W. (not S.62°W.) 25.1 ft. Broken
off and dead. Axe marks and a few faces of
scribing plainly visible on old face where
scribing was cut off.

Cedar now 36", N.69°E. (not N.69°W.) 21.0ft. (not
25.1 ft.) Scribing visible on open face "T27S
R1W".

Corner falls in White Creek. Could not set corner is this
location. Set Witness Corner 10 ft. East of corner.

Set Brass cap at cor. mkd: County Surveyors Office
T27S R2W W.C. | S30 R1W
10' W. to corner | S31
1962

Did not find rock set for corner.

Blaze and rescribe NE. tree:

36" Cedar N.51°E., 11.9 ft. mkd. "T27S R1W W.C. S30
CS BT".

Did not rescribe SE. BT which bears S.36°E., 32.0 ft. from
brass cap.

Survey by Ronald A. Quimby LS #1654 - For: U.S. Forest
Service - May 1980 - M 83-78

Found - 30" Cedar bears S.36°E., 32.0 ft. to old 10' W.C.
with visible scribes.

36" Cedar bears N.51°E., 11.9 ft. to old 10' W.C.
with visible scribes.

True corner is in White Creek, not found.

Set 2½" Iron pipe with 3" brass cap mkd. "W.C T27S R2W S25
R1W S30 S31 W 36.5 RLS 1654 1980."

New BTs- 30" Cedar bears S.18°W., 30.2 ft. scribed "T27S R1W
S31 W.C. BT"

36" Cedar bears N.66°W., 18.5 ft. scribed "T27S R1W
S30 W.C. BT"

Set fiberglass post 2.0 ft. East. Brass washer RLS 1654 in
BT face.

True corner lies 36.5 ft. West of Witness Corner.