

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 202700

PRIMARY CORNER DESCRIPTION Sec. Cor. for 31 & 32 only, T26-1

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO survey by Fred Mensch, Deputy Surveyor, under Contract #797, dated April 19, 1910 - (DCSO records Vol. 10 Page(s) 4101-02)

Set a basalt stone 16x10x8 ins., 11" in the ground for cor. of secs. 31 and 32, marked with 5 notches on E. and 1 notch on W. edge, from which
A Cedar 24" dia., bears N.34°E., 12 lks. dist. mkd. T26S R1W S32 BT.
A Hemlock 12" dia., bears N.19°W., 33 lks. dist. mkd. T26S R1W S31 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Dec. 4, 1969 - C.S. File 54/94-40 (PG 2) & C.S. File 54/94-71

Found - No trace of stone.
24" now 36" Cedar N.34°E., 7.9 ft., rotten face.
12" now 15" Hemlock N.19°W., 21.8 ft. scribe visible, rotten face.

Set Brass cap at cor. mkd: County Surveyors Office
T26S R1W S 31 | S 32
T27S S 5
1969

Reblazed and rescribed:
36" Cedar N.34°E., 7.9 ft. mkd. T26S R1W S32 CS BT.
15" Hemlock N.19°W., 21.8 ft. mkd. T26S R1W S31 CS BT.

Douglas Co. Surveyors Office - John M. Powell, and crew - Nov. 13, 1970 - C.S. File 54/94-40 (PG 2)

Set from rod set as reference pins. See notes in file and renewal visit in 1969. This corner lies 25 ft. North of new road. Also, 116.4 ft. East of sec. cor. to secs. 5 & 6 only, T27S R1W. RESET brass cap in proper location, from bearing trees:
36" Cedar N.34°E., 7.9 ft. scribed T26S R1W S31 CS BT.
15" Hemlock N.19°W., 21.8 ft. scribed T26S R1W S31 CS BT.