

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 cor Secs 20 & 29

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 resurvey by Homer D. Angell, Deputy Surveyor, under contract #747, dated May 5, 1902 - (DCSO rec Vol 11 Pg) 4845)

Set a basalt stone 20x10x6", 15" in the ground for 1/4 sec. cor. mkd. 1/4 on N face, from which
A hemlock, 24" dia., bears N.56°E., 38 lks., mkd: 1/4 S20 BT
A hemlock, 24" dia., bears S.40°W., 38 lks., mkd: 1/4 S29 BT

Douglas Co. Surveyors Office - John Powell - Frank Jones & W. Penley - Dec. 1969 - C.S. File 54/94-80

Found - Unrecorded 5/8" I.R. but no trace of corner stone.
24" now 28" hemlock N.56°E., 25.1 ft. found open face scribe of S20 BT
24" Hemlock now 25" snag S.40°W., 25.1 ft. found burnt face no scribe.
Set - Brass cap at bearings & dist. from both BTs & by 5/8" IR, mkd: COUNTY SURVEYORS OFFICE T27S R1W
1969 1/4 S 20
S 29
Rescribed BT - 28" Hemlock N.56°E., 25.1 ft. mkd: 1/4 S20 CS BT
New BT - 5" Fir, N.36°W., 40.7 ft. scribed "1/4 S20 CS BT"
No BTs in range to south of line.
This corner lies in a cutting unit.

Ronald A. Quimby, LS 1654 & Romanso E. Ware, LS 1005 - For: USFS - March 1980 - M79-32

Found - Douglas County Surveyors brass cap on 1" iron pipe. 8" D.Fir bears N.36°W., 40.1 ft. (Rec. 40.7 ft) with good scar.
32" Hemlock snag bears N.56°E., 25.1 ft with visible scribe.
24" Hemlock snag bears S.40°W., 25.1 ft. with burnt face.
New BTs- 6" D.Fir bears S.20°E., 48.6 ft. scribed "1/4 S29 BT Brass washer in B.T. face RLS #1005.
Note - Found 3/4" Iron Rod 0.2 ft. south of corner.

Fd. Ok by K. Hoffine 7/1995 - M122-27

John Ransom, USFS - Jonathan Drew - 1/2011 - CS File 65/72-16

Found - 1" Iron Pipe with 2 1/2" County Surveyors Office Brass Cap Projecting 15" above ground, cap marked "T27S R1W S20 1/4 S29 1969" "County Surveyors Office"
3/4" rebar South 0.2 ft. no cap.
continued next page

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 240300

PRIMARY CORNER DESCRIPTION 1/4 or Secs 20 & 29

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

19" Fir N.36°15'W., 39.8 ft. healed single blaze.
INDT stump S.39°15'W., 24.4 ft decayed rotting stump
9" Fir snag S.18°30'E., 48.5 ft. scribing visible on
Part. healed single blaze.

New - Painted BTs red with 6" wide band at head height,
painted face blaze, new nails on tags. Added New
Tree:
16" Fir bears S.51°45'W., 18.2 ft scribed "¼S29"
"BT" on double blaze 17.6' to washer.
All new trees include a ¾" brass washer nailed
between B and T on lower blaze, Washer stamped
"LS2561"

Note - Corner is on a flat, in an old clear cut unit approx
700' south of Road 2792. Follow posted line south
from 2792 crossing of N-S centerline of S20.
PLANE COORDINATE POSITION DATA
State OR Zone UTM-10M
North 4782824
East 512619
Estab. By GCDB

Gerald Nygren - For: Seneca Jones Timber Co - 12/2015 - M170-40

Found - 1969 Co. Surveyor Brass cap & BT per (rec.)
20" D.Fir bears N.36°15'W., 39.8' healed face.
Unidentified 3' tall rotten stump, bears S.39°15'W.,
24.4', visible scribe.
9" D.Fir snag, 12' tall, bears S.18°30'E., 48.5',
visible scribe.
17" D.Fir, bears S.51°45'W., 18.2', healed face.

New BTs- 11" Hemlock, bears N.34°E., 8.6', scribed: ¼ S20 BT.
13" D.Fir, bears N.80°W., 20.3', scribed: ¼ S20 BT.

All new BTs established per this survey were measured to a
alum. nail with a ¾" brass washer marked "RLS 1035" in the
side center at the base of said trees. Bearings are to the
face of said trees to the nearest ¼°.