

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 300100

PRIMARY CORNER DESCRIPTION Sec. Cor. for 32 & 33 only (South)

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

GL0 survey by S.C. Flint, Contract #473, dated June 5, 1883  
-(DCSO records Vol. 11 Page(s) 4768)

-----  
Set post 48x4 ins. firmly in the ground for stan. cor. to  
secs. 32 and 33 marked S C T27S R1W on N.; S33 on E.; and S32  
on W. faces, with 4 notches on the E. and 2 on W. edges, from  
which

A Fir 15" dia., bears N.28°E., 129 lks. dist. mkd. T27S  
R1W S33 BT.

A Fir 7" dia., bears N.28°W., 97 lks. dist. mkd. T27S R1W  
S32 BT.

A Fir 8" dia., bears S.3°W., 8 lks. dist. mkd. S BT.

GL0 survey by Homer D. Angell, Deputy Surveyor, under  
Contract #746, dated May 5, 1902 - (DCSO records Vol. 11  
Page(s) 4776-77)

-----  
(76.35 chs.)

Old sec. cor. on line which I destroy.

(80.00 chs.)

Set a Hemlock post 3 ft. long, 4" sq., 24" in ground for  
stan. cor. of secs. 32 and 33, marked S C T27S R1W on N.; S33  
on E.; and S32 on W. faces with 4 grooves on E. and 2 grooves  
on W. faces, from which

A Fir 10" dia., bears N.56°E., 25 lks. dist. mkd. T27S R1W  
S33 BT.

A Fir 18" dia., bears N.42°W., 43 lks. dist. mkd. T27S R1W  
S32 BT.

Douglas Co. Surveyors Office - John M. Powell, and crew -  
Jan. 9, 1970 - C.S. File 54/94-1

-----  
Found - No trace of Hemlock cor. post, but found one good BT  
and one down BT.

10" D.Fir now 14" windfall, N.56°E., 16.5 ft., shows  
open rotted face, no scribing.

18" D.Fir now 29", N.42°W., 28.4 ft., opened and  
found scribing of "3" and other marks.

Set Brass cap at cor. mkd: County Surveyors Office

T 27 S R 1 W

S 32 | S 33

S 5

T 28 S

1970

New BTs- 36" D.Fir N.18°W., 27.4 ft. "T27S R1W S32 CS BT."

18" D.Fir N.20½°E., 41.5 ft. "T27S R1W S33 CS BT."

This cor. lies 10.4 ft. West of the cor. for 4 & 5, T28-1.