

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 2 & 3

Alias	Description

GLO resurvey by Homer D. Angell, Deputy Surveyor, under contract #747, dated May 5, 1902 - (DCSO records Vol. 11 Page(s) 4820-1)

Set a basalt stone 15x10x5", 10" in the ground for ¼ sec. cor. mkd. ¼ on W face, from which
A hemlock, 28" dia., bears N.62°E., 47 lks., mkd: ¼ S2 BT.
A hemlock, 24" dia., bears S.75°W., 53 lks., mkd: ¼ S3 BT.

BLM dependent resurvey by Jasper M. Sams & Donovan C. Harris, Cadastral Surveyors, under Group No. 747, surveyed June/Aug. 1971 - (DCSO records Vol. 35 Page(s) 14574-5)

The sec. cor. of secs. 2 and 3, monumented with the orig. basalt stone, 15x10x5", firmly set, protruding 5" above the ground, mkd. ¼ on W. face.
from which the remaining original bearing tree
A badly burned hemlock stump, size indeterminate, bears N.60°E., 4.7 lks., no marks visible. (Record, N.62°E.)
Set an iron post, 28" long, 2½" dia., 22" in the ground, with brass cap marked:
T27S R1W
¼
S 3|S 2
1971

No suitable trees within limits
Deposit orig. stone alongside the iron post.

Ronald Quimby & Romano Ware, BHW Eng. - For: US Forest Service - Aug. 1980 - M79-55

Found - 1971 BLM brass cap on 2½" iron pipe, properly mkd.
New BTs- 9" Fir, S.73°W., 101.3 ft. "¼ S3 BT"
6" Pine, N.72°E., 108.0 ft. "¼ S2 BT"
Brass washer marked RLS #1654 set in BT faces. Set post & sign 5.0 ft. W.