

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 24 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 survey by Homer D. Angell, Deputy Surveyor, under Contract #746, dated May 5, 1902 - (DCSO records Vol. 11 Page(s) 4796) and (Dup. Pg. 9834, Vol. 23)

A basalt stone 15x12x10 ins., 10" in ground for 1/4 sec. cor. marked 1/4 on W. face, from which
A Fir 18" dia., bears S.61°E., 30 lks. dist. mkd. 1/4 S19 BT.
A Fir 24" dia., bears N.59°W., 22 lks. dist. mkd. 1/4 S24 BT.

GL0 resurvey by Otto L. Draper, U.S. Transitman, under Special Instructions, dated Dec. 24, 1920 - (DCSO records Vol. 23 Page(s) 9844-45)

Intersect the old 1/4 sec. cor. established for secs. 19 & 24, which is a basalt stone 9x6x10 ins. above ground, marked 1/4 on W. face. I change this cor. to refer to sec. 24 only, destroying the old scribe marks in the SE. bearing tree. Alongside of old stone cor. ;
Set an iron post 3 ft. long, 1" in dia., 27" in the ground, for the 1/4 sec. cor. of sec. 24 only, with brass cap marked:
1/4 S24 |
1927

from which
A Fir 22" dia., bears S.61°E., 30 lks. dist. mkd. 1/4 S19 BT. (Old BT)
A Fir 30" dia., bears N.59°W., 22 ks. dist. mkd. 1/4 S24 BT. (Old BT)
A Fir 32" dia., bears S.40°W., 40 lks. dist. mkd. 1/4 S24 BT. (Old BT)

Survey by Burton W. Holt - Wit: Jim Coon - Dec. 3, 1960 - C.S. File 51/100-2

As determined by old BTs:
32" Fir S.40°W., 26.4 ft., scribes and tree in good condition.
The 30" Fir, N.59°W., 14.5 ft. was removed in road construction.
22" Fir, S.61°E., 19.8 ft., new stump with face where scribes were purposely destroyed.
Line tree 13.2 ft. North.
Old stone mkd. 1/4 but the brass cap and pipe are missing.
Set 1/2" x 36" Iron rod with 1" sq. nut at top for corner and set new BT, which is (Cont. Next Page)

TOWNSHIP 27 RANGE 01 POINT IDENTIFIER # 700340

PRIMARY CORNER DESCRIPTION E. 1/4 Cor. for Sec. 24 only

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

46" D.Fir bears S.72°W., 29.8 ft. to face of tree, mkd. ¼
S24 BT on bark.
This corner is approx. 80 ft. South of the Cloburn Sale Road
and 50 ft. S. of W. 1/4 Cor. sec. 19, T27S R1E.

Douglas Co. Surveyors Office - John M. Powell, and crew -
Oct. 22, 1969 - C.S. File 54/94-6

Found - 1" Iron bolt at ¼ corner.
Orig. 22" D.Fir now out of ground, S.61°E., 19.8
ft., tree on face.
Orig. 30" D.Fir, now stump out of ground, N.59°W.,
14.5 ft. scribe visible.
Orig. 32" now 34" D.Fir S.40°W., 26.4 ft. tree
opened, scribe visible. Ring count in correct to
face.
42" D.Fir S.72°W., 29.8 ft. (face) bark scribed "¼
S24 BT"

No trace of 1927 GL0 brass cap.
Set Brass cap at cor. mkd: County Surveyors Office
R T 27 S R
1 ¼ S 24 | 1
W | E
1969

Reblazed and rescribed:
42" D.Fir S.72°W., 31.6 ft.
Original distance between corner of 19 & 24 is 88.4 ft. I
find it 46.0 ft.