

TOWNSHIP 27 RANGE 02E POINT IDENTIFIER # 340100

PRIMARY CORNER DESCRIPTION 1/4 Cor. Sec. 33, South

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO resurvey by Lincoln Wilkes, USCE, under Group No. 62, Special Instructions dated Dec. 21, 1920, surveyed Sept 1926/Aug. 1927 - (DCSO records Vol. 24 Page(s) 10372-3  
-----

Set an iron post, 3 ft. long, 1" dia., 27" in the ground, for standard 1/4 sec. cor., with brass cap mkd.

SC  
1/4 S 33

1927

from which

A fir, 42" dia., bears N.28°E., 27 lks., mkd: 1/4 S33 SC BT.

A cedar, 10" dia., bears N.32°W., 47 lks. mkd: 1/4 S33 SC BT  
-----

Note: See GLO Survey by Samuel C. Flint, Under Contract #473, dated June 5, 1883 (DCSO Records Vol. 24 Page(s) 10358) for orig. 1/4 corner that was destroyed by Lincoln Wilkes