

Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____
Alias_____	Description_____

GLO survey by S.C. Flint, Contract #454, dated June 19, 1882 (DCSO records Vol. 12 Page(s) 4859-60) and (Dup. Pg.4982)

Set Cedar post 4 ft. long, 4"sq., firmly in the ground for cor. to secs. 18, 19, 12 and 24 with 3 notches on the N. and S. edges, from which
A Cedar 30" dia., bears N.80°E., 114 lks. dist. mkd. T27S R2W S18 BT.
A Cedar 10" dia., bears N.80°W., 42 lks. dist. mkd. R3W S13 BT.
A Fir 30" dia., bears S.50°W., 100 lks. dist. mkd. R3W S24 BT.
A Fir 30" dia., bears S.38°E., 29 lks. dist. mkd. S19 BT.

GLO Resurvey by Morris Wygant, Compassman for Zachariah Derrick, U.S. Deputy Surveyor, Under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4912)

The cor. of secs. 13, 18, 19 and 24 which is a post firmly set marked and witnessed as described by the Surveyor General and which I now change to refer to secs. 13, and 24, T27S R3W only.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Dec. 29, 1966 - C.S. File 54/40-2

Found - Orig. 30" now 38" Fir S.38°E., 19.1 ft. This BT was obliterated in 1911 retracement of range line, only fragmentary bark scribing remaining \ / U. NE. and NW. BTs gone, no trace. Found a large hole where SW. BT would have been, old blazes to N. of corner.
Set Brass cap at cor. mkd: County Surveyors Office
R T 27 S R
3 S 13 | 2
W S 24 | W
1966
New BTs- 8" W.Fir S.67°W., 5.7 ft. mkd. T27S R3W S24 CS BT.
8" W.Fir N.70½°W., 15.9 ft. mkd. T27S R3W S13 CS BT
Corner lies on West slope approx. 440 ft. N. of C.C.
Also find 36" Cedar, West 38 ft., out of place, axe blazed and fragmentary scribe with good "S". Does not look like original.

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 100407

PRIMARY CORNER DESCRIPTION Sec. Cor. for 13 & 24 only, T27-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCSO records Vol. 56 Page(s) 22039)

The cor. of secs. 13 and 24 only, remonumented by the Douglas County Surveyors Office in 1966, monumented with an iron post, 1½" dia., projecting 30" above ground, loosely set in a mound of stone, 3 ft. base to top, with brass cap (properly) mkd.

from which the remains of an original bearing tree

A sawed fir stump, 38" dia., bears S.38°E., 19.1 ft., with no marks visible.

and bearing trees mkd. by the Douglas County Surveyors Office

A fir, 17" dia., bears S.69¾°W., 6.3 ft., with a healed double blaze.

A fir, 12" dia., bears N.66½°W., 15.9 ft., with a healed double blaze.

Reset the iron post, 36 ins. long, in place, 24 ins. in the ground, and deposit two Mag-Nails at the base of the iron post.

Ronald L. Rice, Ward NW - For: Seneca Jones Co. - April 2011 - M162-30

Found - 1966 Douglas County brass cap with the following accessories:

18" W.Fir bears S.69¾°W., 6.3' - healed face

12" W.Fir bears N.66½°W 15.9' - healed face

38" D.Fir stump bears S.38°E., 19.1' - rotted face