

PRIMARY CORNER DESCRIPTION 1/4 Cor. for Sec. 6; & S. 1, T27-3

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO survey by S.C. Flint, Contract #454, dated June 19, 1882 (DCSO records Vol. 12 Page(s) 4857) (and dup. pg. #4980)

Set Chinquapin post 3 ft. long, 4" sq., firmly in the ground for ¼ sec. cor. marked on E. and W. faces, ¼ S., from which
 A Laurel 5" dia., bears N.15°W., 36 lks. dist. mkd. ¼ S BT
 A Fir 36" dia., bears N.35°E., 42 lks. dist. mkd. ¼ S BT.

BLM Corner Remonumentation by Harold D. Corbin, Cadastral Surveyor, under Group #'s 350 and 412, Surveyed Aug/Nov. 1958 - (DCSO records Vol. 29 Page(s) 12443)

The ¼ sec. cor., determined at record bearing and distance from the two original bearing trees:
 A Fir 55" dia., bears N.35°E., 42 lks. barks scribing ¼S.
 A rotted Madrone stump, bears N.15°W. 36 lks no marks remaining.

At the corner point
 Set an iron post, 28" long, 2 1/2" dia., 25" in the ground, with brass cap mkd:

T 27 S	
R 3 W ¼	R 2 W
S 1	S 6
1958	

from which

A Fir 18" dia., bears S.62°E., 36 lks. dist. mkd. ¼ S6 BT.
 A Cedar 6" dia., bears S.51°W., 45 lks. dist. mkd. ¼ S1 BT

Fd. & used on BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #983, surveyed May/Aug 1979 - (DCSO records Vol. 44 Page(s) 16929)

BLM resurvey by James E. Jelley and Wayne L. Rogers, Cadastral Surveyors, under Group #1093, surveyed Sept/Oct. 1982 - (DCSO records Vol. 45 Page(s) 17501-02)

The ¼ sec. cor., monumented with an iron post 2½" dia., firmly set, projecting 4" above ground, with brass cap mkd. in 1958, from which the remains of an orig. bearing tree:
 A sawed Fir stump 59" dia., bears N.35°E., 42 lks. dist., with fragmentary scribe marks visible on bark blaze.
 and the remains of the bearing trees mkd. by Corbin:
 A sawed Fir stump 26" dia., bears S.62°E., 36 lks. dist., with healed blaze.
 A Cedar 21" dia., bears S.51°W., 45 lks. with healed blaze and a new bearing tree
 A Grand Fir 11" dia., bears N.19°E., 125 lks. mkd. ¼ S6 BT