

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 32 only

Alias	Description

GLO resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4952)

Set a fir post, 3 ft. long, 4" sq., 24" in the ground, for ¼ sec. cor. mkd ¼ S31 on W & 32 on E face, from which
 A fir, 12" dia., bears S.44°10'E., 16 lks., mkd: ¼ S32 BT.
 A fir, 12" dia., bears N.3°30'W., 19 lks., mkd: ¼ S31 BT.
Derricks ¼ sec. cor. which I now destroy, bears W 400 lks.
Note 1 - We have no record of Derrick setting this corner.
 JC DCSO 9/2008
Note 2 - Per Letter from Portland BLM, this corner is for S32 only. C.S. 63/166 (not scanned)

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Frank Jones - V. Perron - Nov. 1968 - C.S. File 54/40-125

Found - ¾" IR at corner point, unrecorded
 Orig. 12" now 18" fir, alive, S.44°E., 10.6 ft., shows good scar, rescribed: ¼ S32 CS BT
 Orig. 12" now 13" fir 5' high stub, N.3½°W. 12.5 ft. scribe visible on unhealed blaze, badly decayed.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T27S R2W OFFICE 1968 ¼|S 32
New BT - 30" D.Fir, N.32°E., 21.6 ft. mkd: ¼ S32 CS BT
This corner lies on steep NE slope in old growth fir timber approx. 460 ft. north of ridge top.

Romanso E. Ware & Ronald Quimby - For: US Forest Service - July 1980 - M79-49

Found - 1968 County Brass cap. 1968
 30" Fir stump, N.32°E., 21.6 ft. vis. scribe
 18" Fir stump, S.44°E., 10.6 ft. Good scar
New BTs- 28" Fir, N 70°W., 45 4 ft "¼ S32 BT"
 32" Fir, S.24°W., 36.5 ft. "¼ S32 BT"
 Brass washers marked RLS 1005 set in BT faces
No trees in Sec. 32. Set post & sign 5.0 ft. North.

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCSO records Vol. 56 Page(s) 21998-9)

The ¼ sec. cor. of sec. 32 only, remonumented by the Douglas Co Surveyors Office in 1968, perpetuated by Ware and Quimby in 1980, monumented with an iron post, 1¼" dia., firmly set, projecting 6" above ground, with BC (properly) mkd. cont.

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 200140

PRIMARY CORNER DESCRIPTION West 1/4 Cor. Sec. 32 only

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

from which the remains of the original bearing trees
A tin-capped, sawed fir stump, 17" dia., bears S.41¼°E., 11.5 ft., with fragmentary scribe marks visible on a partially healed blaze. (Record, S.44°10'E., 10.6 ft., rescribed by the Douglas County Surveyors Office)
A roothole bears N.3°30'W., 12.5 ft., no trunk remains. and remains of a BT mkd. by the Douglas Co. Surveyors Office
A tin-capped fir stump, 30" dia., bears N.27°E., 20.2 ft., with no marks visible on a decayed blaze.
and remains of bearing trees mkd. by Ware and Quimby
A sawed fir stump, 29" dia., bears S.22°W., 33.2 ft., with scribe marks ¼ S32 visible on a partially healed blaze.
A sawed fir stump, 20" dia., bears N.74½°W., 42.7 ft., with scribe marks ¼ S32 BT visible on a partially healed blaze.
and new bearing trees
A fir, 10" dia., bears N.22½°E., 6.0 ft., mkd. ¼ S32 BT.
A fir, 10" dia., bears S.85°E., 10.5 ft., mkd. ¼ S32 BT.