

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GL0 resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4930)

Set a cedar post, 3 ft. long, 4" sq., 24" in the ground for cor. to secs. 29, 30, 31, & 32, marked T27S S 29 on NE, R2W S 32 on SE, S 31 on SW, S 30 on NW faces, with one notch on S & 5 notches on E edges; from which
 A cedar, 30" dia., bears N.42°30'E., 63 lks., mkd: T27S R2W S29 BT.
 A cedar, 12" dia., bears S.63°30'E., 29 lks. mkd: T27S R2W S32 BT.
 A hemlock, 24" dia., bears S.48°W., 12 lks., mkd: T27S R2W S31 BT.
 A hemlock, 8" dia., bears N.5°W., 47 lks., mkd: T27S R2W S30 BT.
Derricks cor. for secs. 29, 30, 31, & 32 which I now destroy bears N.64°30'W., 320 lks.
Note - We have no record of Derrick setting this corner.
 JC DCSO 9/2008

Thomas E. Shrum, Jr. - For: US Plywood Corp. - Nov. 1962 - C.S. File 51/254-5

Found - 1½" I.P. set in 1954 from Orig. BTs. All trees have blown down or destroyed. I now replace iron pipe with 2½" alum. cap & reference.
Set - 2½" Aluminum Cap
 7" Yew, S.39°W., 45.8 ft. mkd: S31 BT
 15" Hemlock Stump N.3°E., 33.7 ft. Mkd. S29 BT.
 17" Hemlock, N.51°W., 58.8 ft. mkd. S30 BT.
 16" Cedar S.45°E., 14.9 ft. mkd: S32 BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Frank Jones - V. Perron - Dec. 1968 - C.S. File 54/40-151

Found - 2½" Alum. Cap set by U.S. Ply.
 17" Hemlock, now badly burned stump, N.51°W. 58.8 ft., blaze destroyed.
 All other BTs destroyed by logging.
Set - 6 ft. Steel Fence Post alongside Alum. Cap.
New BTs- 26" D.Fir N.8°W., 161.0 ft. mkd: T27S R2W S30 CS BT.
 16" W.Fir N.89°E., 117.6 ft. mid: T27S R2W S29 CS BT
No trees available to south. This corner lies in logged-off unit on moderate N.E. slope.

continued next page

1

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 200200

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

BLM dependent resurvey by A. Bert Skeesick & Timothy J Moore, Cadastral Surveyors & Robert H Browning, Survey Technician, under Group No. 1968, surveyed Aug. 2003/July 2004 - (DCSO records Vol. 56 Page(s) 21999-22000)

The cor. of secs. 29, 30, 31, & 32, perpetuated by person(s) unknown in 1954, from original evidence no longer in existence, remonumented by Shrum, in 1962, perpetuated by the Douglas County Surveyors Office in 1968, monumented with an iron post, 1" dia., firmly set, projecting 15" above ground, with aluminum cap (properly) mkd.

from which the remains of a bearing tree mkd. by Shrum

A sawed, decayed, burnt cedar stump, 29" dia., bears S.49¼°E., 14.9 ft., no marks visible.

and remains of BTs mkd. by the Douglas Co Surveyors Office

A fir snag, 16" dia., bears N.88¼°E., 118.0 ft., with blazed face and axe marks visible.

A sawed, decayed fir stump, 27" dia., bears N.7¼°W., 161.6 ft., no marks visible.

and new bearing trees

A fir, 6" dia., bears N.21¼° E., 30.5 ft., mkd. T27S R2W S29 BT.

A fir, 11" dia. bears S.74°E. 9.2 ft. mkd. T27S R2W S32 BT

A fir, 7" dia. bears S.60¼°W. 5.0 ft. mkd. T27S R2W S31 BT

A fir, 11" dia., bears N.82½°W., 41.9 ft., mkd. T27S R2W S30 BT.