

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 6

Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____
Alias	Description
_____	_____

GLO Survey by Samuel C. Flint, Under Contract #459, dated Aug. 3, 1882 (DCSO Records Vol. 12 Page(s) 4883)

Set laurel post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S on E & W faces; from which
 A fir, 32" dia., bears S.60°E., 22 lks., mkd: 1/4 S BT.
 A fir, 30" dia., bears S.80°W., 52 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - J. Heritage - V. Perron - June 4, 1969 - C.S. File 54/40-169

Found - OBTs as follows:
 Orig. 32" now 38" fir S.60°E., 14.5 ft. Alive frag. bark scribe visible.
 Orig. 30" now 48" fir S.80°W., 34.3 ft. Alive bark scribe "1/4 S BT" visible.
Set - At corner point set 1" IP, brass cap mkd:
 COUNTY SURVEYORS T27S R2W
 OFFICE 1969 1/4 S 6 | S 5
 9" Pine N.49°E., 26.3 ft. mkd: 1/4 S5 CS BT.
 8" D.Fir N.47°W., 6.4 ft. mkd: 1/4 S6 CS BT.
This cor. lies on Southerly slope in old growth timber.

BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #983, surveyed May/Aug 1979 - (DCSO records Vol. 44 Page(s) 16920)

The 1/4 sec cor of secs. 5 & 6, perpetuated & recorded by Tracy in 1969, monumented with an iron post, 1 1/4" dia., firmly set, projecting 9" above ground, with brass cap (properly) mkd. from which the remains of the orig. BTs
 A root hole, bears S.60°E., 22 lks., with sawed fir stump alongside, 38" dia., no marks visible.
 A fir, 45" dia., bears S.80°W., 53 lks., with scribe marks 1/4 S BT visible on bark (Rec. 52 lks.)
and the remains of the BTs mkd. by Tracy
 A root hole, bears N.49°E., 40 lks., with a down pine, 12" dia., alongside, with healed double blaze.
 A fir, 10" dia., bears N.51 1/2°W., 9 1/2 lks., with scribe mark S visible on partially healed blaze.
and a new BT
 A fir, 5" dia., bears S.68 1/2°E., 164 lks., mkd: 1/4 S5 BT.

Fd. BC & 3 BTs by R. Rice 2/2011 - M162-6

continued next page

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 200640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 5 & 6

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Douglas Co. Surveyors Office - Crew: Stephen Flause & Jeff Lorsung- 1/12/2023 - C.S. File 67/55-23

Found - DCS0 brass cap (properly mkd) on 1¼" iron pipe proj. 9".

Rotted-burnt 44"x35' Fir snag S.80°W., 35.0 ft.
15" D.Fir N.51½°W., 6.0 ft. (rec. 9½ lks, 6.27 ft.)
Filly healed blaze, added 3½" mag nail right side center.

21" D.Fir S.68½°E., 108.2 ft. healed scar.
Galvanized steel lath North 0.5 ft.
New - 14" D.Fir S.89°E., 15.9 ft. 3½" mag nail right side center.

Note - Cor. is approx. 85' ENE of end of gravel road.
Compass decl. 14½°E.

Lat: 43°15'01.26" N Long: 122°58'17.00" W