

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

| Alias | Description |
|-------|-------------|
| _____ | _____ |
| Alias | Description |
| _____ | _____ |
| Alias | Description |
| _____ | _____ |
| Alias | Description |
| _____ | _____ |

GLO resurvey by Morris Wygant, Compass man for Zachariah M. Derrick U.S. Dep. Surveyor, under contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4935-6)

Set a Cedar post, 3 ft. long, 3" sq., 24" in the ground, for 1/4 sec. cor., marked 1/4 S22 on W. & 23 on E face; from which
 A cedar, 16" dia., bears S.58°15'E., 38 lks. mkd: 1/4 S23 BT
 A cedar, 12" dia., bears S.24°15'W., 35 lks. mkd: 1/4 S22 BT
Derricks 1/4 sec cor which I now destroy bears N.25°E., 495 lks

Thomas E. Shrum, Jr. - For: US Plywood Corp. - Nov. 1962 - C.S. File 51/254-6

Found - 1 1/2" IP. This IP was set by me in 1954 from the Orig. BT; subsequent logging destroyed all Orig. BTs. I now set a 2 1/2" alum. cap in place of the pipe.
Set - 2 1/2" alum. cap.
60" cedar stump N.37°W., 53.0 ft. mkd: 1/4 S22 RE4287
30" cedar stump S.58°E., 39.6 ft. mkd: 1/4 S23 RE4287

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Frank Jones - V. Perron - Nov. 1968 - C.S. File 54/40-126

Found - US Plywood alum. cap in place & BTs. (1962)
60" Cedar Stump N.37°W., 53.0 ft. scribed "1/4 S22" & tag #4287.
30" Cedar stump S.58°E., 39.6 ft. scribed "1/4 S23"
New BTs- 10" hemlock (Schoolmarm) N.53°W., 47.2 ft. mkd: "1/4 S22 CS BT"
8" D.Fir S.39°E., 45.5 ft. mkd: "1/4 S23 CS BT"
Set - 6.0 ft. steel fence post alongside Brass cap.
This corner lies at foot of NW slope in marshy area.

John Ransom, USFS - Jonathan Drew - 1/2011 - CS File 65/72-18 & M162-52 (JUNE 2011)

Found - 2 1/2" Alum Cap laying on ground detached from pipe. Fd 1" pipe sub-surface and upright in original position.
Set monument over pipe as described below.
60" Cedar Stump N.38°15'W., 52.7 ft Ileg. Frag. scribe visible on single blaze
30" Cedar Stump S.59°15'E., 38.1 ft "1/4 S23 BT" visible on barkless stump single blaze 7" Fir growing out of top
25" Fir S.40°15'E., 44.6 ft healed double blaze
19" Hemlock N.53°15'W., 47.4 ft healed double blaze
continued next page

TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 500340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 22 & 23

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

| | | |
|---|---|---------------|
| Set - | Basis of Bearing for BTs is S.89°45'E., between ¼ and CW1/16 S23 per CSF # M-79-44 Douglas County 3½" Alum Cap on 2½" Alum Pipe projecting 8" above mound of stone. Set directly over found 1" Iron Pipe, Stamped: T27S R2W ¼ S22 S23 LS 2561 2011 Painted 6" Band around BTs and painted face blazes, new nails on signs, cleared brush around corner. | |
| Note - | Corner on level ground just East of Forest Road 2701-300, Follow 2701 to 300 Spur on Right, continue to 100 FT North of PVT Clearcut to the West, Walk East approx 200 FT along toe of south facing hill to corner. Corner lies in marshy area about 20 feet North of toe of slope | |
| REMARKS | | |
| | Rec Bearings/Distances to BTs | |
| Fd Alum Post 3.1 ft. N.78°E. | 60" Cedar Stump N.37°W 53.0 FT | |
| Fd T-iron Post approx 4 ft. N | 30" Cedar Stump S.58°E 39.6 FT | |
| Record bearings & distances to BTs do not converge do not converge to the corner position, new measurements are reported above. | 19" Hemlock N.53°W 47.2 FT | |
| | 25" Fir S.39°E. 45.5 FT | |
| | PLANE COORDINATE | POSITION DATA |
| | State OR | Zone UTM-10M |
| | North | 4783615 |
| | East | 507149 |
| | Estab. By | GCDB |