TOWNSHIP 27 RANGE 02 POINT IDENTIFIER # 500620

PRIMARY CORNER DESCRIPTION S 1/16 Cor. Secs. 2 & 3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

BLM dependent resurvey by Harold D. Corbin, Cadastral Surveyor under Group #351, surveyed July/Aug. 1957 - (DCSO records Vol. 29 Page(s) 12206-7)

Point for the S 1/16 sec. cor. of secs. 2 & 3
Set an iron post, 28" long, 2½" dia., 24" in the ground, with brass cap marked: S 1/16
S 3|S 2
1957
from which
A cedar, 13" dia., bears S.37°E., 49 lks. mkd: S1/16 S2 BT
A fir, 45" dia., bears S.66½°W., 101 lks. mkd: S1/16 S3 BT

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Frank Jones - V. Perron - Dec. 1968 - C.S. File 54/40-159

Found - 1957 GLO brass cap, properly mkd.
13" Cedar now 15" S.37°E., 32.3 ft., shows good scribing.
45" now 50" D.Fir, S.66½°W., 66.7 ft., shows good scar.
New BT - 6" Hemlock N.63°W., 33.2 ft. scribed S 1/16 S3 CS BT
Note - This corner lies on swampy ground.

Fd. & used on BLM Dependent resurvey by Wayne Rogers, Cadastral Surveyor, under Group #983, surveyed May/Aug 1979 - (DCSO records Vol. 44 Page(s) 16924)

Fd. Ok 4/1984 by Geisler, M90-55