

PRIMARY CORNER DESCRIPTION C C for Secs. 1 & 2, T28-2

Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____
 Alias _____ Description _____

GLO resurvey by Fred Mensch , U.S. Cadastral Engineer - under special Instructions, dated June 7, 1922 - (DCSO records Vol. 12 Page(s) 4964)

 Set an Iron post 3 ft. long, 2" dia., 27" in the ground, for closing cor. of sec. 1 and 2 with brass cap marked:

T 27 S R 2 W S35
 S 2 | S 1
 T28S | R2W
 C C
 1923

from which

A Fir 6" dia., bears S.68½°E., 223 lks. dist. mkd. T28S R2W S1 CC BT.

A Fir 9" dia., bears S.5°W., 114 lks. dist. mkd. T28S R2W S2 CC BT.

Douglas County Surveyors Office - Vernon "Ray" Tracy and crew Oct. 1968 - C.S. File 54/40-87

 Found - 1923 GLO brass cap, properly mkd. and in place.
 Orig. 9" now 30" Fir, alive, S.5°W., 75.2 ft. shows good scar.
 Orig. 6" now 24" Fir, alive, S.68½°E., 147.2 ft., shows good scar.

New BTs- 14" D.Fir S.73°W., 12.3 ft. mkd. "T28S R2W S2 CC CS BT.

15" D.Fir S.34°E., 5.0 ft. mkd. "T28S R2W S1 CC CS BT.

Corner lies on steep easterly slope in 2nd growth fir.

Survey by Romano E. Ware - For: U.S. Forest Service - May 1980 - M 79-46

 CONDITION REPORT ONLY

Found - 2" I.P. with 1923 GLO brass cap.

30" D.Fir bears S.5°W., 75.2 ft. with visible scribes.

18" D.Fir bears S.34°W., 5.0 ft. with good scar.

14" D.Fir bears S.73°W., 12.3 ft. with good scar.

24" D.Fir bears S.68°E., 147.2 ft. with visible face.

Set post and sign 3.0 ft. North.