

TOWNSHIP 27 RANGE 03E POINT IDENTIFIER # 340300

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 21 & 28

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO survey by Herbert N Raymond, W.S.C.E., under special instruction, dated Dec. 27, 1920, surveyed Aug. 1929/Aug 1930 - (DCSO records Vol. 24 Page(s) 10106)

Cut a cross (X) on surface rock, 2x2 ft. facing W., for ¼ sec. cor., cut ¼ W. of the cross, and build a mound of stone, 3 ft. base, 1½ ft. high, 2 ft. W. of the cross; from which
A fir, 24" dia., bears S.75½°W., 68 lks., mkd: ¼ S28 BT.
A fir, 24" dia., bears N.61°W., 54 lks., mkd: ¼ S21 BT.

Douglas Co. Surveyors Office - Dennis Gaylord, USFS & Deputy Co. Surveyor - Witness: Bernardino Morales - June 19, 1978 - C.S. File 60/11-19

Condition Report only
Found - A cross (+) in bed rock and a portion of a "4" in the rock just below the cross.
Orig. 24" still 24" D. Fir bears S.75°30'W., 46.4 ft. (Rec. 44.88 ft. is to face). Has a healed blaze.
A 26" D.Fir (Orig. 24") bears N.61°W., 35.64 ft. Has a healed blaze.
Placed County BT signs on both trees. Corner is 5' East of Camas Creek.