

PRIMARY CORNER DESCRIPTION Cor Secs 29, 30, 31, & 32

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5019)

-
- Set cedar post, 4 ft. long, 4" sq., firmly in the ground for cor. to secs. 29, 30, 31, & 32, T27S R3W S29 on NE, S30 on NW, S31 on SW., and S 32 on SE. faces, with 1 notch on S & 5 notches on E edges, from which
- A hemlock, 14" dia., bears N.8°E., 20 lks., mkd: T27S R3W S29 BT.
 - A hemlock, 12" dia., bears N.20°W., 24 lks., mkd: T27S R3W S30 BT.
 - A hemlock, 24" dia., bears S.20°W., 43 lks., mkd: T27S R3W S31 BT.
 - A fir, 72" dia. bears S.35°E. 43 lks. mkd: T27S R3W S32 BT

G. Robert Lecklider - For: Wilbur Lumber Co. - Nov. 1959, filed Dec. 8, 1959 - M 16-57

-
- Found - 72" Fir S.35°E., 28.4 ft. (bark scribe not vis)
14" Hem N.8°E., 13.2 ft. (down, rotten, scribe vis)
12" Hem N.20°W., 15.8 ft. (down, rotten, axe marks vis)
- Set - 6" Hem N.37°E., 19.2 ft.
14" W.R. Cedar N.26°W., 36.1 ft.
16" Hem S.34°W., 52.1 ft.
12" Hem S.7°E., 57.9 ft.

BLM dependent resurvey by Boyd Peterson, Cadastral Surveyor, under Group #1480, surveyed July 1989/May 1990 - (DCSO records Vol. 50 Page(s) 18837-8)

-
- The cor. of secs. 29, 30, 31, & 32, perpetuated by Lecklider, in 1959, determined from the remains of the original bearing trees:
- A root hole, bears N.8°E., 21 lks., with a down, rotted hemlock alongside, 12" dia., no marks visible. (Record, 20 lks.)
 - A sawed fir stump, 72" dia., bears S.35°E., 47½ lks. , no marks visible. (Record, 43 lks.)
- and the remains of bearing trees mkd. by Lecklider
- A sawed hemlock stump, 12" dia., bears N.35°E., 27 lks., with a down hemlock alongside, 10" diam., with fragmentary scribe marks visible on partially healed double blaze.
 - A sawed hemlock stump, 24" dia., bears S.6¼°E., 88 lks., with partially healed blaze.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 29, 30, 31, & 32

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A hemlock, 18" dia., bears S.34°W., 80 lks., with fragmentary scribe marks visible on partially healed double blaze.

At the corner point

Set a stainless steel post, 28" long, 2½" dia., 24" in the ground, with brass cap mkd. T 27 S R 3 W

S 30* S 29
S 31* S 32

1989

from which new bearing trees

A hemlock, 6" dia., bears N.34°E., 110 lks. mkd. X BT.

A hemlock, 9" dia., bears S.89¾°E., 75 lks., mkd. T27S R3W S32 BT.

A hemlock, 10" dia., bears N. 43¼° W., 11½ lks., mkd. T27S R3W S30 BT.

Deposit a white "DEEP-1" magnetic marker at the base of the stainless steel post.

Ken Hoffine - For: Lone Rock Timberland Co. & Seneca Jones Timber Co. - July 2012 - M164-13

- Found - 1989 BLM cap at ground level
- 72" Fir stump bears S.35¼°E., 31.6 ft (record S.35°E., 31.35 ft) no visible marks
 - 13" Hemlock low stump bears N.34¾°E., 17.9 ft (rec. N.35°W., 17.82 ft) no visible marks
 - 15" Hemlock bears N.34°E., 72.9 ft (record N.34°E., 72.6 feet) healed face and tag
 - 15" Hemlock bears N.89½°E., 49.15 ft (rec. S.89¾°E., 49.5 ft) healed face and tag
 - 14" Hemlock bears N.43¼°W., 7.7 ft (record N.43¼°W., 7.59 feet) healed face and tag corner lies on northeast slope approx. 60 feet west of draw