

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 19 & 20

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5023)

Set cedar post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd 1/4 S on E & W faces, from which

A fir, 12" dia., bears N.30°E., 26 lks., mkd: 1/4 S BT.

A fir, 16" dia., bears S.89°W., 7 lks., mkd: 1/4 S BT.

G. Robert Lecklider - For: Wilbur Lbr. Co., Evans Products & US Plywood - Aug. 1960 - M19-51

Found - 28" fir S.30°E., 17.2 ft. rec. N.30°E., rescribed.
 16" fir S.89°W., 4.6 ft rescribed.

Set - Steel tube with survey cap.

BLM dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Garry L. Moore, Surveying Technician, under Group #1416, surveyed Oct. 1987 - March 1988 - (DCSO records Vol. 48 Page(s) 18591-2)

The 1/4 sec. cor. of secs. 19 and 20, perpetuated and recorded by Lecklider, in 1960, monumented with a iron rod, 1/2" dia., firmly set, projecting 4" above ground, with aluminum cap, 1" dia., mkd. PROPERTY CORNER, from which the remains of original bearing trees remarked by Lecklider:

A fir stump, 25" dia., bears S.14 1/2°E., 36 lks., with scribe marks 1/4 S20 RE 4079 visible on the bark blaze. (Rec N.30°E., 26 lks. Lecklider, S.30°E., 26 lks.)

A fir, 20" dia., bears S.89°W., 7 lks., with healed double blaze.

At the corner point
Set a stainless steel post, 28" long. 2 1/2" dia., 22" in the ground, directly over the iron rod, in a rock collar, 3 ft. base, 1 ft. high, with brass cap mkd.

T 27 S R 3 W
 1/4
 S 19 | S 20
 1987

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.
Corner is located 25 lks. N. of a creek, 2 lks. wide, course S.85°E.