

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 200440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 18

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GL0 Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5026)

Set cedar post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd 1/4 S on E & W faces, from which
 A fir, 24" dia., bears N.55°E., 45 lks., mkd: 1/4 S BT.
 A cedar, 36" dia., bears N.22°W., 48 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - S. Bilow - Oct. 14, 1957 - C.S. File 49/14-5

Found - Original 24" now 30" R.Fir N.55°E., 29.7 ft. Shows old bark scribing "4S".
 The original 36" Cedar is down scribing would be under. Checks bearing distance. Seems to be about 3 ft. greater distance than record.
Set Brass Cap at corner mkd 1/4 S18|S17 T27S R3W County Surveyors Office, 1957.
New BTs- 10" R.Fir bears N.32 1/2°W. 10.3 ft scribed 1/4 S18 CS BT
 Cedar bears N.81°E., 22.0 ft. scribed 1/4 S17 CS BT.

BLM dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Garry L. Moore, Surveying Technician, under Group #1416, surveyed Oct. 1987 - March 1988 - (DCSO records Vol. 48 Page(s) 18596)

The 1/4 sec. cor. of secs. 17 & 18, perpetuated & recorded by Byron, in 1957, monumented with an iron post, 1 1/4" dia. firmly set projecting 12" above ground with brass cap (properly) mkd from which the remains of the orig. BTs
 A burned fir snag, 32" dia., bears N.55°E., 45 lks., no marks visible.
 A root hole, bears N.22°W., 48 lks., with a down cedar alongside, size indeterminate, no marks visible.
and the remains of the BTs mkd. by Byron
 A cedar snag, 25" dia., bears N.79°E., 33 lks., with healed double blaze.
 A fir snag, 12" dia., bears N.34 3/4°W., 15 lks., with healed double blaze.