

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

We rescribe, "¼ S7 CS BT" on a single blaze above the present blaze.
This corner is located on a steep north slope along an old cat fire trail.

BLM dependent resurvey by Wayne Rogers, Cadastral Surveyor & Garry Moore, Surveying Tech., under Group #1416, surveyed Oct. 1987 - March 1988 - (DCSO records Vol. 48 Page 18597)

The ¼ sec. cor. of secs. 7 & 8, perpetuated and recorded by Langlitz, in 1975, monumented with an iron post, 1¼" dia., firmly set, projecting 4" above ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree
A burned fir snag, 26" dia., bears S.80°E., 21 lks. no marks visible.
and the remains of the bearing trees mkd. by Corbin
A burned madrone snag, 24" dia., bears S.84½°E., 54 lks., with healed blaze.
A burned cedar snag, 23" dia., bears N.65°W., 57 lks., with healed blaze.

BLM resurvey by A. Bert Skeesick Cadastral Surveyor under Group #1925, surveyed July/Dec. 2000 - (DCSO rec. Vol. 53 Page(s) 20529-30)

The ¼ sec. cor. of secs. 7 & 8, monumented with an iron post, 1" dia., firmly set, projecting 2" above ground, with brass cap (properly) mkd.
from which the remains of an original bearing tree
A burnt fir snag, 24" dia., bears S.75½°E., 13.9 ft., no marks visible. (Record, S.80°E.)
and remains of bearing trees mkd. by Corbin
A burnt madrone snag, 24" dia., bears S.84½°E., 36.2 ft., with a healed blaze. (Record, 35.6 ft.)
A cedar, 27" dia., bears N.63½°W., 37.1 ft., with a healed blaze. (Record, N.65°W., 37.6 ft.)
and a new bearing tree
A fir, 10" dia., bears N.23¾°E., 37.6 ft., mkd. ¼ S8 BT.

Fd. Ok by D. Edwards 11/2006 M151-61

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 12/13/2006 - C.S. File 67/14-50

Found - 2½" dia., DCSO brass cap (properly mkd) projects 3" above ground, firmly set.
continued next page

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 200540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 7 & 8

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Orig. 24" now 26" dia., x 30 ft. tall burnt Fir snag
no marks visible, bears S.80°E., 13.9 ft. (agrees
w/rec.) Orig. BT.

13" now 27" dia., I.Cedar, partially burned on South
side - is alive - fully healed single blaze
visible, bears N.65°W., 37.6 ft. (agrees w/rec.)
1958 BT

22" now 12" dia., x 4 ft. tall madrone stump, east
portion of tree rotted away, illegible scribing
on opened rotted face bears S.84½°E., 35.6 ft.
(agrees w/rec.)

13" dia., D.fir, fully healed single blaze w/BT tag.
This tree not of previous rec. Tag indicates tree
was marked by Devore., bears N.23¾°E., 37.6 ft.
(We agree w/information posted on tag.)

New - 6" dia., D.Fir double blazed & scribed "¼ S8 CS BT"
bears S.66°E., 38.3 ft.

9" dia., D.Fir double blazed & scribed "¼ S7 CS BT"
bears S.27°W., 26.2 ft.

Note - Lies on moderately steep north facing slope in area
of burned trees approx. 50 ft. N or ridge top,
ridge bears ENE

Compass decl. 16½°E.

Fd. as per M151-61 - by D. Edwards, 3/2010 - M160-42