

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 240400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 17 & 20

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5024-5)

Set laurel post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd 1/4 S on N & S faces, from which
A cedar, 24" dia., bears N.29°E., 34 lks., mkd: 1/4 S BT.
A fir, 30" dia., bears S.64°W., 23 lks., mkd: 1/4 S BT.

G. Robert Lecklider - For: Wilbur Lbr. Co., Evans Products & US Plywood - Aug. 1960 - M19-51

Found - 38" Cedar N.29°E., 22.4 ft.
36" Fir, S.64°W., 15.2 ft.
Set - Steel tube with survey cap.

BLM dependent resurvey by Wayne L. Rogers, Cadastral Surveyor & Garry L. Moore, Surveying Technician, under Group #1416, surveyed Oct. 1987 - March 1988 - (DCSO records Vol. 48 Page(s) 18594)

The 1/4 sec. cor. of secs. 17 & 20, perpetuated and recorded by Lecklider, in 1960, from orig evidence no longer in existence; monumented with an iron rod, 1/2" dia., firmly set, buried 3 ft. below ground surface with alum cap, 1" dia., mkd. PROPERTY CORNER, from which th remains of the bearing trees mkd. by Lecklider:

A burned, sawed fir stump, 36" dia. , bears N.73°E., 25 1/2 lks., with scribe marks 4079 BT visible on bark blaze.
A burned fir stump, size indeterminate, bears S.31°W., 36 lks., with a melted bearing tree tag attached.

At the corner point

Set a stainless steel post, 28" long, 2 1/2" dia., 26" in the ground, directly over the iron rod, with brass cap mkd.

T27S R3W
1/4 S 17
S 20
1987

from which a new bearing tree

A burned cedar snag, 13" dia., bears S.31°E., 25 lks., mkd. 1/4 S 20 BT.

Deposit white "DEEP-1" magnetic marker at base of stainless steel post.