

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 300340

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 20 & 21

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5014)

Set laurel post, 3 ft. long, 3" sq., firmly in the ground for ¼ sec. cor. from which
 A cedar, 30" dia., bears S.85°E., 6 lks., mkd: ¼ S BT.
 A laurel, 12" dia., bears N.52°W., 76 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - Milo Godfrey - S. Bilow - May 5, 1958 - C.S. File 49/14-9

Found - Orig 12" now 20" Laurel N.52°W. 50.2 ft., has open face, good scribing "S".
 Shell of 5' Cedar bears S.70°W. 7 ft. This may have been Orig. BT., badly burned, no scribing found.
Set BC at Cor Mkd S20|S21 ¼ County Surveyors Office 1958
New BTs- 16" R.Fir bears S.74°W. 58.0 ft. scribed S20 CS BT
 16" R.Fir bears S.67°E. 21.4 ft. scribed S21 CS BT