

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 300440

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 16 & 17

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5015-6)

-----  
Set laurel post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd 1/4 S on E & W faces, from which  
A cedar, 20" dia., bears S.50°E., 31 lks., mkd: 1/4 S BT.  
A fir, 18" dia., bears N.75°W., 29 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Harold D. Corbin, Cadastral Surveyor under Group No. 350 & 412, surveyed Aug./Nov. 1958 - (DCSO records Vol. 29 Page(s) 12433)

-----  
The 1/4 sec. cor. of secs. 16 & 17, determined at record bearing & dist. from the two orig. BTs:

A cedar, 30" dia., bears S.50°E., 31 lks., bark scribed 1/4 S BT.

A fir, 30" dia., bears N.75°W., 29 lks., bark scribed 1/4 S BT and also axe marks & a healed blaze.

At the corner point

Set an iron post, 28 long, 2 1/2" dia., 26" in the ground, with brass cap marked:

T27S R3W  
1/4  
S 17 | S 16  
1958

from which

A madrone, 10" dia., bears S.20 1/4°E., 42 lks. mkd: 1/4 S16 BT

A madrone, 8" dia., bears N.32 1/4°W., 60 lks., mkd: 1/4 S17 BT