

PRIMARY CORNER DESCRIPTION Cor. Secs. 4, 5, 8, & 9

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

<p>GLO Survey by A.R. Flint & L.L. Williams, Under Contract #151, dated May 23, 1871 (DCSO records Vol. 12 Page(s) 4972)</p> <p>-----</p> <p>Set post to cor. of secs. 4, 5, 8, & 9, from which</p> <ul style="list-style-type: none">A laurel, 15" dia., bears S.1°W., 50 lks.A laurel, 15" dia., bears S.55°E., 45 lks.A fir, 24" dia., bears N.15°E., 30 lks.A fir, 15" dia., bears N.10°W., 15 lks.
<p>GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5017)</p> <p>-----</p> <p>Cor, to Secs. 4, 5, 8, & 9, which is a post, 4" sq., mkd. T27S R3W S4 on NE., S5 on NW., S8 on SW., and S9 on SE. faces, with 5 notches on S. and 4 on E. edges.</p>
<p>Douglas Co. Surveyors Office - B.B. Irving, Deputy CS - Wit. NE Richardson, N.G. Williams, Bert. Delzene - Aug. 11, 1939 - C.S. File 47/66 & 16/55 & "Old" Corner renewal book</p> <p>-----</p> <p>As written in the "Old" Corner renewal book & C.S. 16/55</p> <p>Location identified from all four of the orig BTs as follows:</p> <ul style="list-style-type: none">Laurel 16" dia., S.1°W., 50 lks.Laurel 30" dia., S.55°E., 45 lks.Fir 24" dia., N.45°W., 15 lks. instead of N.10°W., as recorded.Fir 48" dia., N.10°E., _____ lks. instead of N.15°E., 30 lks <p>Set a yew wood post 3"x3"x48" for corner. The orig. fir BTs were reblazed in the bark & scribed.</p> <ul style="list-style-type: none">A Cedar 10" dia., bears S.30°E., 29 lks.A double W.Fir 24" dia., bears S.50°W., 46 lks. <p>As written in C.S. 47/66</p> <p>All OBTS alive & standing</p> <ul style="list-style-type: none">24" Fir N.45°W., 15 lks instead of N.15°W.48" Fir N.10°E., _____ lks instead of 30 lks. <p>Remarked both old firs</p> <p>New BTs-</p> <ul style="list-style-type: none">10" Cedar S.30°E., 29 lks.24" dbl. W.Fir S.50°W., 46 lks.3x3x48" yew wood post.
<p>Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Jack Heritage - V. Perron - 10/10/1969 - C.S. File 54/40-181</p> <p>-----</p> <p>Found - Scribed stake, out of ground.</p> <ul style="list-style-type: none">24" now 28" D.Fir N.45°W., (face) 9.9 ft. bark scribe visible. 193948" now 50" D.Fir N.10°E., 19.8 ft. shows good scar & bark scribe. continued next page

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Cor. Secs. 4, 5, 8, & 9

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

10" now 13" Cedar, S.30°E., (face) 9.1 ft., partly overgrown, scribe marks visible.
24" W.Fir, now down, S.73°W., (Rec. S.50°W.) 30.4 ft. bark scribe found.
Set - Brass cap at cor. mkd: COUNTY SURVEYORS T27S R3W
OFFICE S 5 | S 4
1969 S 8 | S 9
New BTs- 15" W.Fir S.25°W., 26.7 ft. mkd: T27S R3W S8 CS BT
Reblazed & rescribed -
28" Fir N.45°W., 9.9 ft. mkd: T27S R3W S5 CS BT.
This corner lies at old fence corner, fences running N & W.

BLM dependent resurvey by Boyd Peterson, Cadastral Surveyor, under Group #1480, surveyed July 1989/May 1990 - (DCSO records Vol. 50 Page(s) 18835-6)

The cor. of secs. 4, 5, 8, & 9, perpetuated and recorded by Irving, in 1939, and further perpetuated and recorded by Tracy, in 1969, monumented with an iron post, 1¼" dia., firmly set, projecting 18 ins. above ground, with brass cap (properly) mkd.
from which the remains of original bearing trees
A fir, 61" dia., bears N.15°E., 25 lks., with healed blaze. (Record, 30 lks.)
A fir, 30" dia., bears N.45°W., 17½ lks., with healed double blaze. (Record, N.10°W., 15 lks.)
and a bearing tree mkd. by Irving
A cedar, 16" dia., bears S.30°E., 29½ lks., with healed, double blaze.
and a bearing tree mkd. by Tracy
A grand fir, 22" dia., bears S. 26½° W., 41 lks., with healed, double blaze.
A down fence on the west side of the corner, bears N and S.

Fd. Ok by D. Edwards, 11/2006 - M151-61

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Tech. Group No. 2300 surveyed March/April 2008 - (DCSO records Vol. 56 Pg 21836)

The cor. of secs. 4, 5, 8, and 9, perpetuated by Irving, in 1939, further perpetuated by the Douglas County Surveyors Office in 1969, monumented with an iron post, 1¼" dia., firmly set, projecting 18 ins. above the ground, with brass cap (properly) mkd.
from which the remaining original bearing trees
A fir, 55" dia., bears N.15°E., 16.7 ft., with a healed blaze. (Record, 19.8 ft.) continued next page

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 300600

PRIMARY CORNER DESCRIPTION Cor. Secs. 4, 5, 8, & 9

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

A fir, 29" dia., bears N.43 $\frac{3}{4}$ °W., 11.6 ft., with a healed blaze. (Record, N.10°W., 9.9 ft.)
and a bearing tree mkd. by Irving
A cedar, 18" dia., bears S.27 $\frac{3}{4}$ °E., 19.1 ft., with a healed double blaze.
and a BT mkd. by the Douglas County Surveyors Office
A fir, 25" dia., bears S.27 $\frac{1}{2}$ °W., 25.9 ft., with a healed double blaze.
Corner is located on a gentle NW. slope, on the east side of an un-maintained woven wire fence, extending North and South. (See plat for bearings & distances of the lines)

Fd. OK 12/2017 by R. Quimby C.S. File 65/101-12