

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 340540

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 9 & 16

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5016-7)

Set cedar post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd 1/4 S on N & S faces, from which
A fir, 12" dia., bears S.25°E., 33 lks., mkd: 1/4 S BT.
A cedar, 24" dia., bears N.45°W., 17 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Harold D. Corbin, Cadastral Surveyor under Group No. 350 & 412, surveyed Aug./Nov. 1958 - (DCSO records Vol. 29 Page(s) 12435)

Point for the 1/4 sec. cor. of secs. 9 & 16, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 24" in the ground with brass cap marked:

T27S R3W
1/4 S 9
S 16
1958

from which
A cedar, 16" dia., bears N.66°W., 18 lks., mkd: 1/4 S9 BT.
A fir, 9" dia., bears S.7°E., 58 lks., mkd: 1/4 S16 BT.

Fd. ok, BC & BTs, DCSO VRT May 1969 - C.S. File 54/40
Fd. Ok R. Geisler, 6/12/1986 - C.S. File 63/34