

PRIMARY CORNER DESCRIPTION Cor. Secs. 3, 4, 9, & 10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5009)

-----  
Set laurel post, 4 ft. long, 4" sq., firmly in the ground for cor. to secs. 3, 4, 9, & 10, marked T27S R3W S3 on NE, S 4 on NW, S 9 on SW, S 10 on SE faces, with 5 notches on S & 3 on E edges; from which  
A laurel, 6" dia., bears N.75°E., 42 lks., mkd: T27S R3W S3 BT.  
A laurel, 10" dia., bears N.14°W., 64 lks., mkd: T27S R3W S4 BT.  
A laurel, 6" dia., bears S.65°W., 45 lks., mkd: T27S R3W S9 BT.  
A laurel, 6" dia., bears S.10°E., 38 lks., mkd: T27S R3W S10 BT.

Douglas Co. Surveyors Office - James W. Byron, Deputy - June 12, 1957 - C.S. File 47/193

-----  
Found - NE, NW, and SW orig. BTs all alive and show old faces but have been opened years ago and center rotted and no scribing left. Also I find rotted Laurel-base of orig. SE BT. All BTs check for bearing & distance. All BTs except NW BT are about same size as recorded. The NW BT is now 16"  
Set an iron pipe with brass cap mkd.  
Section corner  $\frac{4}{3}$  T27S, R3W, County Surveyors Office, 1957.  $\frac{9}{10}$   
Blaze and scribed 4 trees  
16" R.Fir, N.18°W., 5.9 ft mkd. T27S R3W S4 CS BT.  
16" R.Fir, S.39½°W., 24.7 ft mkd. T27S R3W S9 CS BT.  
6" R.Fir, N.24½°E., 25.2 ft mkd. S3 CS BT.  
16" R.Fir, S.69½°E., 13.8 ft mkd. T27S R3W S10 CS BT

BLM dependent resurvey by Harold D. Corbin, Cadastral Surveyor under Group No. 350 & 412, surveyed Aug./Nov. 1958 - (DCSO records Vol. 29 Page(s) 12430-1)

-----  
The cor, of secs. 3, 4, 9, & 10, perpetuated & recorded by Byron, in 1957, at record bearing and distance from two remaining original BTs, monumented with an iron pipe, 1" dia. firmly set, 12" above ground, with brass cap (properly) mkd. from which the orig. BTs  
A dead madrone, 8" dia., bears N.75°E., 42 lks., with an old opened and rotted blaze.  
A madrone, 14" dia., bears N.14°W., 64 lks., with an old opened and rotted blaze.  
continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 3, 4, 9, & 10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

and county surveyor's bearing trees:

A red fir, 6" dia., bears N.24½°E., 38 lks., with illegible scribe marks visible on an opened blaze.

A fir, 16" dia., bears S.69½°E., 21 lks., mkd. T27S R3W S10 CS BT on an unhealed blaze.

A fir, 16" dia., bears S.39½°W., 37½ lks., with illegible scribe marks visible on unhealed blaze.

A fir, 16" dia., bears N. 18° W., 9 lks. dist., with illegible scribe marks visible on unhealed blaze.

At the corner point

Set an iron post, 28" long, 2½" dia., 26" in the ground, with brass cap marked:

T27S	R3W
S 4	S 3
S 9	S 10
1958	

from which

A fir, 6" dia. bears N.60½°E., 13 lks. mkd: T27S R3W S3 BT

A fir, 13" dia. bears S.51½°E. 59 lks mkd: T27S R3W S10 BT

A fir, 10" dia. bears S.26½°W. 43 lks. mkd: T27S R3W S9 BT

A fir, 13" dia. bears N.67¾°W. 67 lks. mkd: T27S R3W S4 BT

Deposit County Surveyor's iron pipe alongside iron post.

Fd. & used on BLM dependent resurvey by Lance J. Bishop & Wayne L. Rogers, Cadastral Surveyors, under Group #1189, surveyed May/July 1984 - (DCSO records Vol 47 Pages 17959-60)

Fd. BLM & DCS BC & 5 BTs 5/2007, M153-3. Set 6' post South 2' by D. Edwards. (DCS BC bears N.82°13'26"W., 0.48')

BLM Dependent resurvey by A Bert Skeesick Cadastral Surveyor, and Robert H. Browning, Surveying Tech. Group No. 2300 surveyed March/April 2008 - (DCSO records Vol. 56 Pg 21833)

-----  
The cor. of secs. 3, 4, 9, and 10, perpetuated by Byron, in 1957, from original evidence no longer in existence, remonumented by Corbin in 1958, monumented with an iron post, 2½" dia., firmly set, projecting 7" above the ground (alongside of which is an iron post, 1¼" dia., firmly set, projecting 12" above the ground, with brass cap mkd. COUNTY SURVEYORS OFFICE SEC S3 S4 S9 S10 1957), with brass cap mkd. from which bearing trees mkd. by Byron, reported by Corbin

A fir, 13" dia., bears N.24½°E., 25.1 ft., with a healed blaze.

A fir, 24" dia., bears S.69½°E., 13.9 ft., with a healed blaze.

A fir, 21" dia., bears S.39½°E., 24.8 ft., with a healed blaze.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 3, 4, 9, & 10

Alias	Description
_____	_____
_____	_____
_____	_____
_____	_____

and remains of bearing trees mkd. by Corbin  
A fir, 20" dia., bears S.51½°E., 38.9 ft., with a healed blaze.  
A fir, 16" dia., bears S.26½°W., 28.4 ft., with a healed blaze.  
A sawed fir stump, 15" dia., bears N.67¾°W., 44.2 ft., with no marks visible.  
and a new bearing tree  
A fir, 7" dia. bears N.59½°W., 30.9 ft. mkd T27S R3W S4 BT  
New bearing trees have a 2½"x¼" magnetic nail (Mag Nail) driven at the base on right side center, unless otherwise noted in the corner description.

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral Surveyor, under Group No. 2258, Surveyed April/June 2009 - (DCSO records Vol. 57 Page(s) 22679-80)

-----  
The cor. of secs. 3, 4, 9, and 10, monumented with an iron post, 2½" dia., firmly set, projecting 6" above ground, (alongside of which is an iron post, 1¼" dia., firmly set, projecting 12" above ground, with brass cap (properly) mkd. from which bearing trees mkd. by Byron, in 1957  
A fir, 13" dia., bears N.24½°E., 25.1 ft., with a healed double blaze.  
A fir, 24" dia., bears S.69½°E., 13.9 ft., with a healed double blaze.  
A fir, 21" dia., bears S.39½°W., 24.8 ft., with a healed double blaze. (Record, S.39½°E.)  
and the remains of a bearing tree mkd. by Byron, in 1957  
A roothole bears N.18°W., 5.9 ft., alongside of which is a decayed, uprooted fir, size indeterminate, with no marks visible.  
and bearing trees mkd. by Corbin  
A fir, 21" dia., bears S.51½°E., 38.9 ft., with a healed blaze.  
A fir, 17" dia., bears S.26½°W., 28.4 ft., with a healed blaze.  
A sawed, decayed fir stump, size indeterminate, bears N.67¾°W., 44.2 ft., with no marks visible.  
and remains of a bearing tree mkd. by Corbin  
A decayed fir root crown bears N.60½°E., 8.6 ft., alongside of which is a decayed down fir, size indeterminate, with scribe marks S R3W S3 visible on an open blaze.  
and a bearing tree mkd. by Skeesick and Browning  
A fir, 7" dia., bears N.59½°W., 30.9 ft., with scribe marks T27S R3W S visible on a partially healed blaze.

Cont.

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 400600

PRIMARY CORNER DESCRIPTION Cor. Secs. 3, 4, 9, & 10

Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____
Alias	_____	Description	_____

Ron Quimby - Crew: N. Fromdahl, R Heichel & R Vincent -  
12/2017 - C.S. File 65/101-15

-----

Found - 1958 BLM brass cap - 1957 DCSO brass cap alongside.  
14" D.Fir N.24°E., 25.1 ft, good scar.  
26" Fir S.69°E., 13.9 ft, good scar.  
Other BTs are gone or blown down.  
New - Steel post 2.0 south  
5" cedar N.20°W., 32.4 ft marked X chest high.  
Note - Compass decl. 15½°E.