

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 400640

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 3 & 4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 5010)

Set laurel post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor., from which

A pine, 7" dia., bears S.10°W., 11 lks., mkd: 1/4 S BT.

A fir, 16" dia., bears S.25°E., 7 lks., mkd: 1/4 S BT.

BLM dependent resurvey by Harold D. Corbin, Cadastral Surveyor under Group No. 350 & 412, surveyed Aug./Nov. 1958 - (DCSO records Vol. 29 Page(s) 12431)

Point for the 1/4 sec. cor. of secs. 3 & 4, at proportionate distance; there is no remaining evidence of the orig. corner. Set an iron post, 28 long, 2 1/2" dia., 24" in the ground with brass cap marked:

T27S R3W

1/4
S 4 | S 3
1958

from which

A W.Fir, 10" dia., bears S.16°E., 73 lks., mkd: 1/4 S3 BT.

A cedar, 9" dia., bears N.45 1/2°W., 54 lks., mkd: 1/4 S4 BT.

BLM dependent resurvey by Lance J. Bishop & Wayne L. Rogers, Cadastral Surveyors, under Group #1189, surveyed May/July 1984 - (DCSO records Vol. 47 Page(s) 17960-1)

The 1/4 sec. cor. of secs. 3 & 4, monumented with an iron post, 2 1/2" dia., firmly set, projecting 5" above ground, with brass cap (properly) mkd.

from which bearing trees mkd. by Corbin

A W.Fir, 16" dia., bears S.16°E., 73 lks., with healed blaze.

A cedar, 14" dia., bears N.45 1/2°W., 54 lks., with healed blaze.