

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 420700

PRIMARY CORNER DESCRIPTION West 1/16 Cor. S. 3; & 34 of T.26-3

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Bureau of Land Management Dependent Resurvey by Harold D. Corbing, Group #350 - Survey Aug/Nov., 1958 (DCSO records Volume 29 Pages 12413-14)

Set an iron post 28" long, 2½" dia., 25" in the ground, with brass cap mkd.

W 1/16 $\frac{S\ 34}{S\ 3}$

1958

from which

A Cedar 6" dia., bears N.32°W., 38 lks. dist., mkd.
W 1/16 S34 BT.

A Fir 8" dia., bears S.25¼°E., 15 lks. dist., mkd.
W 1/16 S3 BT.

Doug. County Surveyors Office - Vernon Tracy; Mike Stone; Jack Heritage - Feb. 1966 - C.S. File 54/7-58

Found - 1958 Cad. Brass cap, properly marked.
6" Cedar S.32°W., 25.1 ft. Slash piled on backside of tree, scribe visible, "BT". Appears to be dying.

8" D.Fir S.25¼°E., 9.9 ft. Blaze nearly healed over.
Alive, good condition.

New BT - (?) " Cedar N.24°W., 35.0 ft. mkd. W 1/16 S34 CS BT.
This corner lies on steep, east slope. Brass cap just below large root of fir tree.