

PRIMARY CORNER DESCRIPTION 1/4 Cor Sec. 3; & 34 of T. 26-3

Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_  
Alias \_\_\_\_\_ Description \_\_\_\_\_

Original - Addison R. Flint, Contract #56 dated March, 1855  
(DCSO Records, Volume 10 Page 4352)

-----  
Set ¼ sec. post, from which  
    A Pine 12" dia., bears S.5°W., 52 lks. dist.  
    A Pine 8" dia., bears N.27°W., 122 lks. dist.

Bureau of Land Management survey by Harold D. Corbin, Group  
No. 350, Survey Aug./Nov. 1958 (DCSO records, Volume 29  
Page 12413)

-----  
Found corner monumented with a wooden post, 3 x 3 ins. cross  
section, firmly set, 2½ ft. above ground, and in a mound of  
stone, 2½ ft. base, 6" high, at record bearing and distance  
from the only remaining original bearing tree:

    A down and rooted Pine 20" dia., bears S.5°W., 52 lks.  
    with scribe marks S BT visible on opened blaze.

    At the corner point, set an iron post, 28" long, 2½ ins.  
    dia., 24" in the ground, and in a mound of stone,  
    2½ ft. base, to top, with brass cap mkd.

        T 26 S R 3 W

        ¼        S 34  
                  S 3

                  1958                    from which

    A Cedar 13" dia., bears N.50¾°W., 70 lks. mkd. ¼ S34 BT.

    A Fir 6" dia., bears S.38½°E., 40 lks., mkd. ¼ S3 BT.

Deposit the wood post alongside the iron post.

Fd. OK by B. Shaner, 2/95. M 121-52 - C.S. File 63/161-2

BLM Dependent Resurvey by Kenneth W. Saveland, Cadastral  
Surveyor, under Group No. 2258, Surveyed April/June 2009 -  
(DCSO records Vol. 57 Page(s) 22670)

-----  
The ¼ sec. cor. of secs. 3 and 34 on the N. bdy. of the Tp.,  
monumented with an iron post, 2½" dia. firmly set, projecting  
6" above an embedded collar of stone, with brass cap properly  
mkd.

from which the remains of bearing trees mkd. by Corbin

    A fir, 17" dia., bears S.38½°E., 26.4 ft., with a healed  
    blaze.

    A sawed cedar stump, 25" dia., bears N.50¾°W., 46.2 ft.  
    with a healed blaze.

and a new bearing tree

    A cedar, 9" dia., bears N.70°W., 37.6 ft., mkd. ¼ S34 BT  
Corner is located on a N. slope at the intersection of a  
dilapidated barbed wire fence line, bears N. and E. **CONT**

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 440700

PRIMARY CORNER DESCRIPTION 1/4 Cor Sec. 3; & 34 of T.26-3

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

The geographic position (NAD 1983 (CORS)) of the 1/4 section corner of sections 3 and 34 on the north boundary of the township, as determined by direct occupation, utilizing dual frequency, carrier phase GPS receivers, relative to the National Spatial Reference System (NSRS) Continuously Operating Reference Stations (CORS) "DODSON BUTTE CORS ARP" and National Cooperative CORS Network Station "ROSEBURG COOP CORS ARP", is as follows:  
Latitude: 43°15'25.254"N.      Longitude: 123°02'22.978"W.