

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 540200

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 26 & 35

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 4996)

Set cedar post, 3 ft. long, 3" sq., firmly in the ground for 1/4 sec. cor. mkd on N & S faces, from which
An Alder, 10" dia., bears S.30°W., 7 lks., mkd: 1/4 S BT.
A fir, 24" dia., bears N.26°W., 74 lks., mkd: 1/4 S BT.

Douglas Co. Surveyors Office - John Powell - July 1970 - C.S. File 54/40-188

Reported as not found.
Possible fir stump (Old BT) has old axe face no scribe visible. Come off tree bearing & dist. I hit call on creek about 1 ch West fair, No evidence to renew.

Ronald G. Geisler, LS 1988 - For: Champion International Cor. - Jan. 1984 - M95-77 & C.S. 58/278

Set - 2 1/2" alum. cap set on a 1"x36" iron pipe, properly stamped & with PLS 1988
New - 23" fir bears N.81°W., 16.4 ft. scribed: 1/4 S26 BT.
13" maple bears S.55°W., 33.8 ft. scribed: 1/4 S35 BT.

BLM Dependent resurvey by Boyd W. Peterson & Mark D. Dixon, Cadastral Surveyors, under Group #1268, surveyed May/Sept. 1985 - (DCSO records Vol. 48 Page(s) 18211-2)

The 1/4 sec. cor. of sec. 26 and 35, reestablished by proportionate measurement and recorded by Geisler, in 1984 and is accepted as the best available evidence of the original corner position, monumented with an iron pipe, 3/4 in. diam., firmly set projecting 10 ins., above ground, with an aluminum cap mkd.

T27S R3W
1/4 S 26
 S 35

1983
PLS 1988

from which bearing trees mkd. by Geisler
A maple, 12" dia., bears S.55°W., 51 lks., with scribe marks 1/4 S35 BT visible on partially healed blaze.
A fir, 24" dia., bears N.81°W., 25 lks., with scribe marks 1/4 S26 BT visible on partially healed blaze.

Fd. Alum. cap, 2 BTs and Set 6 ft. steel post 2' south by David Edwards, March 2012, M163-38