

TOWNSHIP 27 RANGE 03 POINT IDENTIFIER # 640400

PRIMARY CORNER DESCRIPTION 1/4 Cor. Secs. 13 & 24

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

GLO Survey by Sam C. Flint, Under Contract #454, dated June 19, 1882 (DCSO Records Vol. 12 Page(s) 4991)

Set cedar post, 3 ft. long, 3" sq. for witness ¼ sec. cor. at 39.00 chs not being able to set it at the proper dist on account of perpendicular cliff of rocks (as stated) from which
A fir, 24" dia., bears North, 66 lks., mkd: ¼ S BT.
A fir, 24" dia., bears N.10°E., 68 lks., mkd: ¼ S BT.

Douglas Co. Surveyors Office - Vernon "Ray" Tracy - Sept 1969 - C.S. File 54/40-179

Not found
W.C. - Sign of old fire, also apparent numerous previous search by others.

Ronald L. Rice, Ward NW - For: Seneca Jones Co. - April 2011 - M162-30

A thorough search was performed for evidence of the 1882 GLO witness corner. With no evidence found, I then set the true 1/4 corner, as described, at proportionate distance between as-tied section corners.

Set - 5/8"x5" rebar in drilled rock with 2½" aluminum cap,
mkd: T27S R3W
¼ S 13
S 24
2011
54633LS

with the following accessories:

- 18" D.Fir bears S.50°E., 39.0' - blazed, scribed "¼ S24 BT"
- 18" D.Fir bears S.3°W., 38.2' - blazed, scribed "¼ S24 BT"
- 11" D.Fir Bears N.89°W., 15.0' - blazed, scribed "¼ S13 BT"

SET - 3/8"x1½" MAG PK nail in drilled vertical rock bearing N.54°W 22.12'