

PRIMARY CORNER DESCRIPTION Sec. Cor. for 25 & 36 only (East)

Alias	Description
Alias	Description
Alias	Description
Alias	Description

GLO survey by S.C. Flint, Contract #454, dated June 19, 1882 (DCSO records Vol. 12 Page(s) 4861) and (Dup. Pg. 4984)

-----  
Set Cedar post 4 ft. long, 4" sq., firmly in the ground for cor. to secs. 36, 25, 31 and 30, marked T27S R2W S30 on NE.; R3W S25 on NW.; S36 on SW.; and S31 on SE. faces, marked with 5 notches on N. and 1 on S. edges, from which

- A Fir 8" dia., bears N.50°E., 24 lks. dist. mkd. T27S R2W S30 BT.
- A Cedar 24" dia., bears N.48°W., 52 lks. dist. mkd. T27S R3W S25 BT.
- A Cedar 8" dia., bears S.30°W., 27 lks. dist. mkd. T27S R3W S36 BT.
- A Fir 24" dia., bears S.68°E., 29 lks. dist. mkd. T27S R2W S31 BT.

GLO Resurvey by Morris Wygant, Compassman for Zachariah Derrick, U.S. Deputy Surveyor, Under Contract #779, dated Feb. 7, 1908 - (DCSO records Vol. 12 Page(s) 4911)

-----  
The cor. of secs. 25, 30, 31 and 36 which is a post, firmly set, marked and witnessed as described by the Surveyor general, and which I now change to refer to secs. 25 and 36 T27S R3W only.

Survey by Ronald Geisler - For: Champion International Co. June/Aug. 1985 - M 90-71

-----  
Set a 2½" aluminum cap on a 2½" x 30" alum. flared pipe, mkd. PLS 1988, from which  
14" Fir bears S.11°W., 11.0 ft. scribed T27S R3W S36 BT.  
7" Fir bears N.45°W., 18.9 ft. scribed T27S R3W S25 BT.