

TOWNSHIP 27 RANGE 04 POINT IDENTIFIER # 100300

PRIMARY CORNER DESCRIPTION Sec. Cor. 19 & 30; S. 24 & 25, T27-5

Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____
Alias _____ Description _____

Original - James E. Freeman Contract #1 dated May, 1851
(DCSO records, Volume 12 Pages 5040 & 5042)

Set post, cor. of secs. 19, 24, 25 & 30, from which
 A B.Oak, 28" dia. bears S.79 3/4°E., 556 lks. dist.
 A B.Oak, 15" dia. bears S.21°30'W., 993 lks. dist.
Make trench as per instructions.

Ben B. Irving, County Surveyor For California Oregon Power
Company - April, 1953 - C.S. 45/150

Set - 1" brass cap 6" below ground, from which
 10d nail in top of anchor post bears N.40°36'E.,
 31.22 ft.
 10d nail in anchor post bears S.41°41'E., ~~12.53~~
 (28.0 ft. M.E.G.)
Metal 6 on C.O.P.C.O. pole # B 6125 bears
 S.80°52'W., 12.53 ft.

Found OK, Don Bentz, August, 1987 - M 101 - 26

Douglas Co. Surveyors Office - Randall W. Smith, Deputy -
Stephen J. Flause - 11/16/93 - C.S. File 64/50-8

Found - 2½" dia., DCSO brass cap on an iron pipe, 12" below
 road surface.
PPL power pole #B6125, bears S.82½°W., 13.2' to
 center of power pole. (Rec. S.80°52'W., 12.53',
 dist. fits well outside edge of pole) 1953 BBI.
Both anchor post recorded in 1953 BBI renewal are
 gone.
New - 5/8" iron rod, 3" below road surface, bears S.63°E.,
 22.5'.
 11" dia., D.Fir, at Northwest corner of property at
 602 O.C. Browning Rd., single small low blaze
 "S19 BT", bears N.11½°E., 115.0'.
PK nail in top center of a 13" dia., 5½' high corner
 post bears S.42 3/4°E., 29.6'.
See sketch in C.S. File 64/50.

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause -
3/17/2008 - C.S. File 67/25-34

Fd. ok as per 1993 DCSO Record.