

PRIMARY CORNER DESCRIPTION Cl. Cor. Secs. 5 & 6 only (North) T28-4

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

GLO Resurvey by W.H. Byars, Under Contract #376 dated Jan. 22, 1881 (DCSO records, Volume 12 Page 5079)

Set ¼ sec. cor. a Fir post from which:
 A Laurel, 6" dia., bears S.14°E., 24 lks.
 A Laurel, 5" dia., bears S.20°W., 26 lks.

BLM Cadastral Dependent Resurvey by Lynn Roseberry, Group No. 636 Survey May/June 1967 (DCSO records, Volume 34 Page 14198-99)

True point for the closing cor. of secs. 5 and 6.
Set a fiberglass post, 28" long, 2½" dia. 24" in the ground with brass cap mkd: T 27 S R 4 W

 S 32

 S 6 | S 5
 CC
T 28 S R 4 W

1967 from which

A Fir 17" dia. bears S.35 3/4°E., 48 lks. dist., mkd.
T28S R4W S5 CC BT.
A Cedar 29" dia. bears S.47¼°W., 61 lks. dist. mkd.
T28S R4W S6 CC BT.

From this point the orig. closing cor. of secs. 5 & 6, bears N.0°08'W., 0.23 chs. dist., monumented with a concrete filled Iron pipe, 1" dia., protruding 3" above ground, firmly set, from which the remaining original bearing tree:

A sawed and rotted Fir stump, 20" dia. bears S.30°E., 43 lks. dist., with scribe marks BT visible on remaining portion of opened blaze.

From this same point, the standard corner of secs. 31 and 32 bears N.89°34'W., 0.71 chs. dist.

Douglas Co. Surveyors Office - John Pike - Stephen J. Flause - 3/13/2008 - C.S. File 67/25-32

Fd. BLM BC, 1 live BT, 2 BT stumps, good cond. & BC at Std. Cor. Secs. 31 & 32 only (T27-4)