

PRIMARY CORNER DESCRIPTION Sec. Cor. for 33 & 34

Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____
Alias _____	Description _____

Original - Addison R. Flint, Contract #56 dated March, 1855 (DCSO Records, Volume 12 Page 5047)

Set post cor. to secs. 33 and 34, from which

- A Laurel 16" dia. bears S.38°W., 150 lks. dist.
- A B.Oak 18" dia. bears S.71°E., 135 lks. dist.
- A B.Oak 14" dia. bears N.42°W., 108 lks. dist.
- A Laurel 15" dia. bears N.18°E., 130 lks. dist.

W.H. Byars, Deputy Surveyor under Contract #376 dated January 22, 1881 - (DCSO records, Volume 12 Page 5080)

Sec. cor. to secs. 4, 3, 33 and 34, set new post as per instructions, bearing trees all standing, viz:

- A Laurel, 11" dia. bears S.38°W.
- A B.Oak 18" dia. bears S.71°E., 135 lks. dist.
- A B.Oak 14" dia. bears N.42°W., 108 lks. dist.
- A Laurel 15" dia. bears N.18°E., 130 lks. dist.

F.C. Frear, Deputy - For: Ingram & Adams - Dec. 11-13, 1918 Volume 3 Page 45 and C.S. File 4/34

Renew from old BTs.
Set in ¾" x 36" galv. iron pipe from which
All old Gov't trees, remarked, still stand.

Bureau of Land Management Dependent Resurvey - Irving Zirpel Jr. & Wm. Glenn under Special Instructions dated August 29, 1957. (DCSO records, Volume 29 Pages 12223-24)

The standard cor. of secs. 3, 4, 33 and 34, determined at record bearing and distance from the only remaining orig. bearing tree marked by Flint in 1855, which was remarked by F.C. Frear, D.C.S. in 1918, as follows:

- A B.Oak 22" dia. bears N.42°W., 108 lks. dist. marked with scribe marks R4W visible on opened blaze.

At the corner point, set an iron post 28" long, 2½" dia. 26" in the ground, with brass cap mkd: S C

T27S R4W
S 33 | S 34
S 4 | S 3
T28S
1958

from which

- A Cedar 15" dia. bears N.48°E., 119 lks. dist. marked T27S R4W S34 SC BT.

continued next page

PRIMARY CORNER DESCRIPTION Cor. Secs. 33 & 34, 3 & 4 T28-4

Alias	Description
Alias	Description
Alias	Description
Alias	Description

A Cedar 15" dia. bears S.23°E., 110 lks. dist. marked T28S R4W S3 SC BT.
A Fir 5" dia. bears S.69¼°W., 137 lks. dist. marked T28S R4W S4 SC BT.
A Fir 13" dia. bears N.12°45'W., 110 lks. dist. marked T27S R4W S33 SC BT.
The corner falls at a fence corner with outcropping of granite and quartz.

Bureau of Land Management Dependent Resurvey by Gordon S. Popken, under Group #850. Survey Sept/Oct. 1974 (DCSO records Volume 36 Pages 14986-87)

Found - 1958 Cadastral Brass cap, firmly set, projecting 6" above ground.
A Cedar 16" dia. bears N.48°E., 119 lks. dist. with healed blaze.
A Cedar 17" dia. bears S.23°E., 110 lks. dist. with healed blaze.
A Fir 16" dia. bears N.12¾°W., 110 lks. dist. with healed blaze.
New BT - A Fir 10" dia. bears S.58°W., 120 lks. dist. mkd. T28S R4W S4 SC BT.

Douglas Co. Surveyors Office - Randall W. Smith, Deputy - Stephen J. Flause - 2/3/2000 - C.S. File 66/14-15

Found - 1958 BLM BC/IP protrudes 6" out of ground corner lies at intersection of N-S & West running fence lines.
14" now rotted to ground Oak evidence of old blaze, no scribing found, bears N.42°W., 71.3 ft. OBT
15" now rotted down Madrone, no blazes or scribing found bears N.18°E., 85.8 ft. OBT
NE & SE BTs from 1958 BLM survey now gone.
5" now 16" dia., D.Fir with a fully healed single blaze, bears S.71¼°W., 91.5 ft. (Rec. S.69¼°W., 90.4 ft.) 1958
13" now 24" dia., D.Fir with a fully healed single blaze, bears N.12 3/4°W., 72.6 ft. 1958
10" now 24" dia., D.Fir with a fully healed single blaze, bears S.56½°W., 79.2 ft. (rec. S.58°W., 79.2 ft.) 1974
New BTs- 14" dia., D.Fir double blazed & scribed "T28S R4W S3 CS BT" bears S.21½°E., 16.3 ft.
Corner lies 5 ft. north of a small seasonal creek in a shallow draw.
No granite & quartz outcropping as noted in 1958 visible at corner.